UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on	Wells
1. Type of Well GAS	5. Lease Number SF-0785036. If Indian, All.or Tribe Name
 Name of Operator Meridian Oil Inc. Address & Phone No. of Operator Box 4289, Farmington, NM 87499 (505)326-9700 Location of Well, Footage, Sec, T, R, M. SWSE Sec.31, T-29-N, R-7-W, NMPM 910'S, 1550'E 	 7. Unit Agreement Name San Juan 29-7 Unit 8. Well Name & Number San Juan 29-7 Unit #118 9. API Well No. 10.Field and Pool Blanco Pictured Cliffs 11.County and State Rio Arriba County, NM
Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back Casing Repair	f Action Change of Plans New Construction Non-Routine Fracturing
In order to evaluate the potential of the Pictural this well, it is intended to isolate the casing packer, and produce the Pictured Cliffs. After evaluation, the well will be plugged or repaired	failure with tubing and sufficient time for d before the end of 1991.
AUG 3 (OIL COIL COIL COIL COIL COIL COIL COIL C	V. DIV. 00 00 00 00 00 00 00 00 00 00 00 00 00
14. I hereby certify that the foregoing is true Signed May Mulhuld (JK) Title Regulatory	· · · · · · · · · · · · · · · · · · ·
(This space for Federal or State office use) APPROVED BY TITLE CONDITION OF APPROVAL, IF ANY:	
	The Carlot Control of the Carlot Control