

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
BURLINGTON RESOURCES
OIL & GAS COMPANY

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
2225' FSL, 2205' FEL, Sec. 14, T-29-N, R-7-W, NMPM, Rio Arriba County

5. Lease Number
Fee
State Oil & Gas Lease #
Lease Name/Unit Name
San Juan 29-7 Unit
Well No.
62B
Pool Name or Wildcat
Blanco Mesaverde
Elevation:

API # (assigned by OCD)
30-039-26073

RECEIVED
MAY 26 1999
OIL CON. DIV.

Type of Submission	Type of Action
☐ Notice of Intent	☐ Abandonment
☒ Subsequent Report	☐ Recompletion
☐ Final Abandonment	☐ Plugging Back
	☐ Casing Repair
	☐ Altering Casing
	☒ Other -
	☐ Change of Plans
	☐ New Construction
	☐ Non-Routine Fracturing
	☐ Water Shut off
	☐ Conversion to Injection

13. Describe Proposed or Completed Operations

3-26-99 MIRU. TIH w/gauge ring to 2222'. (PBTD @ 5647'). Ran CCL-GR @ 0-2222'. Unable to get inside of lnr top. RD.

4-24-99 MIRU. ND WH. NU BOP. TIH w/6 1/4" bit to 2250'. Load hole w/21 bbl 2% KCl wtr. TOOH. SD for Sunday.

4-26-99 TIH w/3 7/8" mill to 2250'. Drill rubber plug & 400' cmt. SDON.

4-27-99 Drill cmt to 3432'. SDON.

4-28-99 Drill cmt to 4608'. TIH to PBTD @ 5647'. Load hole w/2% KCl wtr. Circ out 20 bbl gel, 10 bbl drilling mud. TOOH. SDON.

4-29-99 TIH, ran CBL @ 2100-5647', TOC on 4 1/2" lnr @ 2990'. TOOH. TIH w/mill to PBTD @ 5647'. TOOH. (Verbal approval to squeeze lnr top from Ernie Busch, OCD). TIH w/CIBP, set @ 5618'. TIH w/4 1/2" pkr, set @ 2268'. PT CIBP to 3000 psi, OK. TOOH w/pkr. TIH w/7" pkr, set @ 2100'. Establish injection. Pump 310 sx Class "B" 50/50 poz w/0.25 pps Flocele, 5 pps Gilsonite, 0.4% fluid loss 2% gel. Sqz to 1360 psi. WOC. SDON.

4-30-99 TOOH w/7" pkr. TIH w/6 1/4" bit to 2150'. TOOH. TIH w/3 7/8" bit to TOC @ 2240'. Drill cmt to PBTD. Pump 500 gal 15% HCl. TOOH. SD for weekend.

5-3-99 Perf Menefee/Point Lookout @ 5158-5545'. Frac w/2440 bbl slk wtr, 100,000# 20/40 Arizona sd. Perf Cliff House/Menefee @ 4612-5088'. Frac w/2493 bbl slk wtr, 100,000# 20/40 Arizona sd. TIH w/CIBP, set @ 4550'. PT CIBP to 3000 psi, OK. SDON.

5-4-99 Perf Lewis @ 3863-4506'. SD for weather.

5-5-99 Frac Lewis w/960 bbl 25# linear gel, 200,000# 20/40 Brady sd. CO after frag.

SIGNATURE [Signature] Continued on back
Regulatory Administrator May 26, 1999

no
(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY CHARLIE T. PERRIN DEPUTY OIL & GAS INSPECTOR, DIST. #3 MAY 26 1999
Approved by _____ Title _____ Date _____

5-6-99 Blow well & CO.
5-7-99 Blow well & CO to CIBP @ 4550'.
5-8-99 Drill CIBP @ 4550'. Push CIBP @ 5080'. Blow well & CO.
5-9-99 Blow well & CO.
5-10-99 Blow well & CO to 5080'. Attempt to drill CIBP @ 5080'. TOOH. Work string parted.
Left 3 7/8" mill & 30' tbg. SDON.
5-11-99 TIH w/fishing tools. Fishing. SDON.
5-12/15-99 Fishing. SD for Sunday.
5-17-99 Fishing.
5-18-99 Fishing. TOOH w/fish & fishing tools. TIH w/3 7/8" mill to 5081'. Establish circ.
5-19-99 Mill @ 5081-5200'. Circ hole clean.
5-20-99 Mill to 5505'. Circ hole clean.
5-21-99 TOOH w/mill. TIH w/new 3 7/8" mill to 5505'. Establish circ. Mill to PBTD @ 5618'
Circ hole clean. TOOH. TIH w/177 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 5554'.
ND BOP.
5-22-99 NU WH. RD. Rig released.