Form 3160-5 November 1983) Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR verse side)

SUBMIT IN TRIPLICATE.

Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985

5. LEASE DESIGNATION AND BERIAL NO.

SF-078049 BUREAU OF LAND MANAGEMENT 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS A (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals. 7. UNIT AGREEMENT NAME METE CYBET OTHER ·NOV 1 2 1985 8. FARM OR LEASE NAME 2. NAME OF OPERATOR Tenneco 0il Company <u>Hughes</u> A LS 3. ADDRESS OF OPERATOR 9. WELL NO. **BUREAU OF LAND MANAGEMENT** P. O. Box 3249, Englewood, CO 80155 FARMINGTON RESOUR LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)

At surface FARMINGTON RESOURCE AREA 10. FIELD AND POOL, OR WILDCAT <u>Blanco Mesaverde</u> 11. SBC., T., R., M., OR BLK. AND SURVEY OR AREA 990' FSL, 990' FWL Sec. 27, T29N R8W
12. COUNTY OR PARISE | 18. STATE 15. BLEVATIONS (Show whether DF. BT. GR. etc.) 14. PERMIT NO. 6401' GL <u>San Juan</u> NM 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT EMPORT OF: TEST WATER SEUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL MULTIPLE COMPLETE FRACTURE TREATMENT PRACTURE TREAT ALTERING CARING BHOOTING OR ACIDIZING OTHER Plug off & sidetrack SHOOT OR ACIDIZE ABANDON* REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)* 10/23/85 MIRU. Pmp 20 bbls 1% KCl wtr dwn tbg. Press built to 750 psi & held. Bled off tbg, tbg dead. ND tree & change out rotating head. NUBOP's, closing unit dwn. W/O new closing unit. 10/24/85 Wrkd tbg donut out w/85,000#, worked stuck tbg. Ran free-pt. Tbg stuck @

5,000'. Free @ 4930'. TIH w/1-13/16" jet cutter. Could not go below 4,360'. P00H, RIH w/1-11/16" jet cutter.to 4,930'. Cut 2-3/8" tbg @ 4,930'. R/D Gearhart. Pmp 60 bbls 1% KCl wtr dwn tbg w/no pressure. POOH 2-3/8" tbg. Laid dn 16- jts 2-3/8" tbg. P/U HOWCO drillable cmt retainer, and 2-7/8" D.P., TIH @ 6: a.m.

10/25/85 Set cmt retainer @ 4434'. Press tst csg & pipe rams to 1000 psi for 15 min, o.k. Pmp 400 sxs Howco Lite (736 ft3) followed by 100 sxs (118 ft3) Class B w/2% CaCl2. Sqz press 1600 psi. Reversed out 1/2 bbl cmt. POOH. Drill mousehole NDBOP & tree. NU BOP & spool Test blind rams to 1000 psi for 30 mins. O.K.

10/26/85 Drill retainer & dress cmt to 4550'. TOOH. Cut drilling line. PU knuckle jt & 4-3/4" bit. TIH, drill to 4570'. TOOH. PU 6-1/4" hole opener & ream 4550-4570'.

10/27/85 Ream around dog leg. TOOH. Left hole opener in hole. RIH openended to crew into H.O. TOOH. Recov'd H.L. TIH to drill. Drill & survey.

18. I hereby certify that the foregoing, is, true and correct		
SIGNED Stoth Mixtury	TITLE _	Senior Regulatory Anlayst DATE ///7/85
		6 6 1 M C 18 502 052209
(This space for Federal or State office use)		
APPROVED BY	TITLE _	DAME
CONDITIONS OF APPROVAL, IF ANY:		NOV 2 0 1985

OIL CON. PIN. SW *See Instructions on Reverse Side NMOCC