

ANDERSON-PRICHARD OIL CORPORATION



DISTRICT IV FIELD OFFICE

SUITE B-400, NEW U. S. NATIONAL BANK BUILDING

1740 BROADWAY

DENVER, COLORADO

GENERAL OFFICE

LIBERTY BANK BLDG.

OKLAHOMA CITY 2, OKLAHOMA

PHONE KEYSTONE 4-1849

January 13, 1959

Our File:

DNM-3-B

(P-C)

New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico

Attention: Mr. Emery C. Arnold

Subject: #1 Prichard-Federal
SW NE Section 6-29N-8W
San Juan County, New Mexico

Dear Mr. Arnold:

Thank you for notifying us of the discrepancy in the reported location of the subject well. This confusion resulted evidently from two different surveys. We are enclosing a photostatic copy of the original survey made by Mr. C. O. Walker dated August 10, 1952, which indicates the location of this well to be 2269' east and 1650' south of the northwest corner of Section 6-T29N-R8W. This should be the same as 1650' FNL and 1650' FEL of Section 6.

In event you desire that we submit corrected reports, please advise.

Yours very truly,


CHARLES M. HEARD
District Superintendent

Encl.

CMH:rw



COMPANY Anderson Prichard Oil Corporation
Well Name & No. Prichard- Federal No. 1 Lease No. _____
Location 2269 Feet East and 1650 Feet South of the NW corner,
Being in The SW¹ of the SE¹
Sec. 6, T 29 N., R 8 W., N.M.P.M., San Juan County, New Mexico
Ground Elevation 6050 - Graded



Scale -- 4 inches equals 1 mile

Surveyed August 10, 19 52

This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

E. O. Walker
Registered Professional
Engineer and Land Surveyor.

Seal:

Farmington, New Mexico