

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	5. LEASE DESIGNATION AND SERIAL NO. <u>SE-028487</u>
2. NAME OF OPERATOR <u>Aztec Oil and Gas Company</u>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>Drawer 570, Farmington, New Mexico</u>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>1650 FNL &amp; 1650 FEL, Sec. 4-29N-8W</u>	8. FARM OR LEASE NAME <u>Hill</u>
14. PERMIT NO.	9. WELL NO. <u>#2</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>6387 Gr</u>	10. FIELD AND POOL, OR WILDCAT <u>Blanco Mesaverde</u>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 4-29N-8W</u>
	12. COUNTY OR PARISH <u>San Juan</u>
	13. STATE <u>New Mexico</u>

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to:

Cut off 2-3/8" tubing and pull same  
Squeeze open hole 4700' to 5566'  
Set whipstock at 4650'  
Drill with gas to TD 5550'  
Perforate and frac Mesaverde zone  
Run 2-3/8" tubing.

RECEIVED

MAY 19 1969

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED Joe C. DelaneyTITLE District SuperintendentDATE 5-8-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side