UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

2. Name of Operator RESOURCES OIL & GAS COMPANY	Sundry Noti	ces and Reports on Well	s (1) 1:3/	
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 9. API Well No. 30045201800 4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool Planco PC 11:80' FSL, 1170' FWL, Sec. 14, T-29-N, R-08-W, NMPM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action X Notice of Intent Recompletion Subsequent Report Plugging Back Casing Repair Abendonment Altering Casing Conversion to Injection X Other - Restimulation 13. Describe Proposed or Completed Operations 1. Pull 2 3/8' tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)			5. 6.	SF 078415-A If Indian, All. or
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 9. API Well No. 30045201800 4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool Blanco PC 1180' FSL, 1170' FWL, Sec. 14, T-29-N, R-08-W, NMPM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action X Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back Casing Repair Abtering Casing Conversion to Injection X Other - Restimulation 13. Describe Proposed or Completed Operations 1. Pull 2 3/8' tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)		Fig. ned	100 M.	Unit Agreement Name
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 9. API Well No. 30045201800 4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool 1180' FSL, 1170' FWL, Sec. 14, T-29-N, R-08-W, NMFM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action X Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment X Other - Restimulation 13.Describe Proposed or Completed Operations 1. Pull 2 3/8" tubing 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out 5. Run Tubing. 6. Return well to production. Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)	2. Name of Operator BURLINGTON RESOURCES OIL 8		Mills as	
PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 1180' FSL, 1170' FWL, Sec. 14, T-29-N, R-08-W, NMPM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action X. Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Altering Casing Conversion to Injection X. Other - Restimulation 13. Describe Proposed or Completed Operations 1. Pull 2 3/8" tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I bereby certify that the foregoing is true and correct. Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)			8.	
4. Location of Well, Footage, Sec., T, R, M 1180' FSL, 1170' FWL, Sec. 14, T-29-N, R-08-W, NMPM 11 County and State Co, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission X Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Attering Casing Conversion to Injection X Other - Restimulation 13.Describe Proposed or Completed Operations 1. Pull 2 3/8" tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I befely certify that the foregoing is true and correct. Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)	_		9.	API Well No.
11. County and State Co, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action _X Notice of Intent Abandonment Change of Plans _Recompletion New Construction _Subsequent Report Plugging Back Non-Routine Fracturing _Casing Repair Water Shut off _Altering Casing Conversion to Injection X Other - Restimulation 13. Describe Proposed or Completed Operations 1. Pull 2 3/8" tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production.	_			Field and Pool
Type of Submission X Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Altering Casing Conversion to Injection X Other - Restimulation 13.Describe Proposed or Completed Operations 1. Pull 2 3/8" tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I befeb certify that the foregoing is true and correct. Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)	1180° FSL, 1170° FWL, Sec. 1	4, 1-29-N, R-08-W, NMPM		County and State
X Notice of Intent Abandonment Change of Plans Recompletion New Construction Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection X Other - Restimulation 13.Describe Proposed or Completed Operations 1. Pull 2 3/8" tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I bereb certify that the foregoing is true and correct. Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)	12. CHECK APPROPRIATE BOX TO IND	ICATE NATURE OF NOTICE,	REPORT, OTHER	DATA
Recompletion New Construction Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection X Other - Restimulation 13.Describe Proposed or Completed Operations 1. Pull 2 3/8" tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I bereb certify that the foregoing is true and correct. Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)	Type of Submission	Type of Act	ion	
Subsequent Report Casing Repair Water Shut off Final Abandonment Z Other - Restimulation 13.Describe Proposed or Completed Operations 1. Pull 2 3/8" tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I hereby certify that the foregoing is true and correct. Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)	<u>X</u> Notice of Intent		_	
Casing Repair Water Shut off Altering Casing Conversion to Injection X Other - Restimulation 13.Describe Proposed or Completed Operations 1. Pull 2 3/8" tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I bereb certify that the foregoing is true and correct. Signed Title Requiatory Administrator Date 12/2/99 (This space for Federal or State Office use)				
	Subsequent Report			-
1. Pull 2 3/8" tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I bereby certify that the foregoing is true and correct. Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)	Final Abandonment	Altering Casing Conversion to Injection		
1. Pull 2 3/8" tubing. 2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I bereby certify that the foregoing is true and correct. Signed Title Regulatory Administrator Date 12/2/99	13.Describe Proposed or Complete		1011	
2. Clean out to PBTD. 3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I hereby certify that the foregoing is true and correct. Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)				
3. Acidize and foam fracture treat PC zone. 4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I bereby certify that the foregoing is true and correct. Signed	1. Pull 2 3/8" tubing.			
4. Clean out. 5. Run Tubing. 6. Return well to production. 14. I hereby certify that the foregoing is true and correct. Signed	2. Clean out to PBTD.			
5. Run Tubing. 6. Return well to production. 14. I kereby certify that the foregoing is true and correct. Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)		re treat PC zone.		
6. Return well to production. 14. I bereby certify that the foregoing is true and correct. Signed				
14. I hereby certify that the foregoing is true and correct. Signed	5. Run Tubing.			
Signed Title Requlatory Administrator Date 12/2/99 (This space for Federal or State Office use)	6. Return well to producti	on.		
Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)				
Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)				
Signed Title Regulatory Administrator Date 12/2/99 (This space for Federal or State Office use)				
Signed Title Requlatory Administrator Date 12/2/99 (This space for Federal or State Office use)				
Signed Title Requlatory Administrator Date 12/2/99 (This space for Federal or State Office use)				
Signed Title Requlatory Administrator Date 12/2/99 (This space for Federal or State Office use)				
Signed Title Requlatory Administrator Date 12/2/99 (This space for Federal or State Office use)				
(This space for Federal or State Office use)	14. I hereby certify that the	foregoing is true and o	correct.	
	Signed Jeggy Ole	Title Regulatory Adm	ministrator Da	te 12/2/99
APPROVED BY			- -	
			Date	12/20/99

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Roelofs A #5

Blanco PC Field Section 14M, T29N, R08W San Juan County, NM

Wellbore Schematic

