	*See	Instructions on R	everse Side	FARMINGIUM RESOURCE AREA
APPROVED BY CONDITIONS OF APPROVA		ritle		- OCT 1 1 1985
(This space for Federal or S	•			DIST. 3
18. I hereby certify that the for		TITLE Senior	Regulatory Analy	
10 11 11				RECEIVE
	jts 1-1/4" tbg and	d perf'd sub		-1/4" tbg and perf'd IH. RIH w/5-1/2" overshot
psi. BDSIP = 90 ps sealers. Good ball KB to knock balls o dwn csg w/70Q foam.	i. Acidize dn tbo action. Flush ac f perfs. PUH to 2 Total 70,000 gal	g w/2000 gal cid to btm p 2865. Blow l, 119,000#	s. 15% HCL and erf. Release pk well dry w/N2. 20-40 sand, ATR	135 1.1 s.g. ball or and RIH to 3160' RU Dowell and frac
9/27/85 RU Geahart 2 JSPF = 3025-66', pkr to 2865' KB. S	3119-23'. (45' -	90 holes)	RIH w/91 jts 2-3	premuim charge csg gun at 3/8" tbg and fullbore
off bottom. Tag bo at 3200' KB change	ttom at 5628' KB. out tbghead. RIH Pressure tst csg	Rig up Gea 90 jts2-3/8	rhart. Set mode " tbg w/SN 2 jt	string weight to get el D pkr on wireline off bottom. Roll hole eld o.k. Rig up Gearhart
17. DESCRIBE PROPOSED OR COMPL proposed work. If well i nent to this work.) *	ETED OPERATIONS (Clearly stats directionally drilled, give su	te all pertinent deta		es, including estimated date of starting any tical depths for all markers and sones perti-
PRACTURE TREAT BHOOT OR ACIDIZE REPAIR WELL (Other)	MULTIPLE COMPLETE ABANDON* CHANGE PLANS		PRACTURE TREATMENT BHOOTING OR ACIDIZING (Other) Dual P.C.	ALTERING CASING ABANDONMENT* lits of multiple completion on Well apletion Report and Log form.)
NOTICE	OF INTENTION TO:		SUBS	EQUENT REPORT OF:
16. Ch	eck Appropriate Box To	Indicate Nature	of Notice, Report, or	i San Juan i NM r Other Data
14. PERMIT NO.	15. ELEVATIONS (Sh	OW whether DF, RT, G	GTON RESOURCE AREA	Sec. 19, T29N R8W 12. COUPTY OR PARISH 18. STATE
925' FNL, X 850' FWL		BUREAU	OF LAND MANAGEMENT	11. SEC., T., E., M., OR RLE. AND SURVEY OR AREA
4. LOCATION OF WELL (Report I See also space 17 below.) At surface	ocation clearly and in accorda	ince with any State	requirements.*	10. FIELD AND POOL, OR WILDCAT Blanco Mesaverde
P. O. Box 3249, En		5 RE	CEIVE	9. WBLL NO.
Z. HAMB OF OPERATOR Tenneco Oil Company				8. FARM OR LEASE NAME Hughes LS
OIL GAB WELL XX	OTBER	···		7. UNIT AGREEMENT NAME
SUNDRY (Do not use this form f	NOTICES AND RE or proposals to drill or to de- application for permit	PORTS ON epen or plug back to —" for such proposes	WELLS a different reservoir.	and an analysis of Island NATS
	BUREAU OF LAND MAI	NAGEMENT	/	SF-078046 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Form 3160-5 Notember 1983) Formerly 9-331) DE	UNITED STAT PARTMENT OF THI	TES E INTERIOR	SUBMIT IN TRIPLICAT (Other instructions on verse side)	Budget Bureau No. 1004-0135
				Form approved.

70m 3160-5 November 1983) Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR verse side)

SUBMIT IN TRIPLICATES (Other instructions on re-

Form approved. Budget Eureau No. 1004-0135 Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SF-078046

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS	

BUREAU OF LAND MANAGEMENT

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICA"	HON FOR PERMIT— 10	auch proposition		
OIL GAB WELL OTHER			7. UNIT AGREEMENT NAME	
2. HAME OF OPERATOR		•	8. FARM OR LEASE NAME	
Tenneco Oil Company			Hughes LS	
8. ADDRESS OF OPERATOR			9. WELL NO.	
P. O. Box 3249, Englewood	od, CO 80155		1A	
 LOCATION OF WELL (Report location ele See also space 17 below.) 	arly and in accordance wit	th an R'E CCEETS VED	10. FIELD AND POOL, OR WILL	CAT
At surface			Blanco Mesaverd	
ODEL ENL MOEGL ELL		OCT 09 1985	11. SBC., T., B., M., OR BLK. AN SURVEY OR AREA	Т
925' FNL, X 850' FWL			Sec. 19, T29N R	8W
14. PERMIT NO.	15. ELEVATIONS (Show whe	ther MUREAU-OR LAND MANAGEMENT	12. COUNTY OR PARISH 18.	BTATE
	6408' GL	FARMINGTON RESOURCE AREA	San Juan	NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF I	TENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SEUT-OFF PRACTURE TREAT	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF REPAIRING WELL PRACTURE TREATMENT ALTERING CABING
BHOOT OR ACIDIZE	ABANDON* CHANGE PLANS	SHOOTING OR ACIDIZING ABANDONMENT*
(Other)		(Norz: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)*

9/30/85 RIH w/3-1/8" overshot dressed w/2-3/16" spriral grapple. Latched onto fish at 5420'. POOH w/tbg, overshot and fish. RIH w/89 jts of 1-1/4" tbg on 2-3/8" tbg. Tag fill at 5480. CO w/foam at 5608'. Could no go deeper. RIH and tagged up at 5608' after flowing 2 hrs.

10/1/85 Acidize mesaverde w/1000 gal 15% HCL. RIH and tag btm. Had 30' of fill. C0 PBTD w/foam. POOH. RIH w/2-3/8" longstring and land at 5488'. RIH w/1-1/4" shortstring and land at 3115'. NDBOP. NUWH. RDMOSU.

Need Completion RepRECEIN and correct TITLE Senior Requaltory Analyst DATE ACCEPTED FOR (This space for Federal or State office use) APPROVED BY 1 1 1985 CONDITIONS OF APPROVAL, IF ANY: FARMINGTON RESOURCE AREA ee Instruction