Form 3160-5 November 1983) Formerly 9-331)	UNITED S DEPARTMENT OF BUREAU OF LAND	THE INTERIC	SUBMIT IN TRIPLICAT (Other instructions on verse side)	76- 5. L	Budget Eureau No Expires August 3 EASE DESIGNATION AN SF-078046	1, 1985 VD BERIAL NO.
SUN (Do not use this	DRY NOTICES AND form for proposals to drill or to Use "APPLICATION FOR PEI	REPORTS O	N WELLS ck to a different reservoir. posais.)	6. 11	F INDIAN, ALLOTTEE C	DE TRIBE NAME
I. OIL GAS				7. 0	MIT AGREEMENT NAM	t
WELL WELL 2. NAME OF OPERATOR	X. OTHER			8. 7	ARM OR LEASE NAME	
Tenneco Oil	Company				Huahes	
3. ADDRESS OF OPERATOR				9. W	BLL NO.	
P. O. BOX 3	249, Englewood, Copport location clearly and in ac	0 80155 cordance with any Sc	tate requirements.*	10.	PIELD AND POOL, OR	WILDCAT
See also space 17 belo At surface	(₩.)				Basin Dakota	
1020' FNL,	810' FEL		- 1	11.	SEC., T., R., M., OR BLI SURVEY OR AREA	K. AND
~	•.				Sec. 29, T29	N. R8W
14. PERMIT NO.		S (Show whether DF, II	tT, GR, etc.)		COUNTY OR PARISH	13. STATE
	6396	' GL			San Juan	NM
16.	Check Appropriate Bo	x To Indicate No	iture of Notice, Report, o	r Other	Data	
1	NOTICE OF INTENTION TO:	İ	BUB	BEQUENT B	SPORT OF:	
TEST WATER BHUT-OF	PULL OR ALTER	i—i	WATER SHUT-OFF		REPAIRING WE	LL
FRACTURE TREAT	MULTIPLE COMP	ETE X	FRACTURE TREATMENT		ALTERING CAS	
SHOOT OR ACIDIZE REPAIR WELL	ABANDON® CHANGE PLANS		SHOOTING OR ACIDIZING (Other)		ABANDONMENT	
(Other)			(Norm: Report res	ults of mu impletion	iltiple completion on Report and Log form	Well
	uests permission to the attached details.	ailed procedu				
			R	SEP.	E	
18. I hereby certify that	the foregoing is true and corre		ior Regulatory Ana	yst A	DATE	L1985
(This space for Fede	ra or State office use)					
APPROVED BYCONDITIONS OF AF	PPROVAL, IF ANY:	TITLE		-	SEP 0 9 1985	5
				1	tov SKU	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instructions on Reverse Side

APPAREA MANAGER FARMINGTON RESOURCE AREA

228'				
99' 92' kota: 7274' 7370' 7470'	-90 -80 78			7314'
7528 '	77	515'	CIBF)

4820	
LEASE Hughes	
WELL NO. 4	
CASING:	
9-5/8"OD, 36 LB, K-55 CSG.W/ 180	sx
TOC @ surf . HOLE SIZE 12-3/4 DATE:8-	05-79
REMARKS	
7 "OD, 23 LB,K-55 CSG.W/ 650	sx
TOC @ HOLE SIZE 8-3/4"DATE: 8-	1079
REMARKS	
10.5	
4-1/2"OD, 11.6 LB, K-55 CSG.W/ 525	sx
TOC @ 3499.HOLE SIZE 6-1/4 DATE 8-	27-79
REMARKS TOL @ 3499'	
TUBING:	
2-3/8 "OD, 4.7 LB, J-55 GRADE 8 RD, EUE	CPLG
LANDED @ 7314'. SN, PACKER, ETC.	

DETAILED PROCEDURE:

- MIRUSU. Kill well w/2% KCl wtr. NDWH, NUBOP. RIH & tag PBTD. CO w/foam if necessary. Tally out of hole w/tbg.
- Set Model D pkr w/exp plug @ 3450' on W.L. Dump 2 sxs sd on pkr. Load hole w/2% KCl water. PT csg to 2500 psi. NDBOP and replace single tbg head w/dual tbg head. NUBOP.
- Run (R-CBL-CCL From 3450' TO CEMENT TOP.
 3. Run cased hole GR-CNL-CCL from 3450' to
 1450'. Telecopy results to Denver.
- 4 Perforate the PC as per G.E. recommendation w/4" premium charge csq qun and 2 JSPF.
- 5. RIH w/7" fullbore pkr., SN and 2-3/8" tbg Set pkr ± 150' above perfs. PT casing to 500 psi. Break down perfs w/2% KCl wtr. Acidize PC dn tbg w/40 gal per perf'd foot weighted 15% HCl and 50% excess ball sealers. Release pkr and RIH past perfs. Blow hole dry w/N2. POOH w/tbg, SN & pkr.

PROCEDURE - PAGE 2

LEASE	NAME:	Hughes	WELL	NUMBER:	4

- 6. Frac PC dn csg w/70 quality foamed 2% KCl water and 20/40 sd @ 2500 psi max. Use attached design graph to calculate volumes. Call Denver to confirm design. SI for 2 hrs and flow back to pit thru 1/2" tapped bull plug.
- 7. Kill well w/2% KCl water. RIH w/2-3/8" tbg w/muleshoe on btm and F/N w/exp check valve 1 jt off btm. Position seal assembly and blast joints to land the tbg @ ± 7350' with blast jts across from PC intervals. CO to Model D pkr w/foam. Knock out plug and land 2-3/8" long string.
- 8. RIH w/1-1/4" tbg W/SN, pump out plug and perforated, orange peeled sub on btm. Land short string @ ± btm of PC perfs.
- 9. NDBOP, NUWH. Pump out check valve from long string. Swab in Dakota if necessary. Pump out plug in short string and kick around w/N_2 . FTCU.
- 10. SI PC for AOF.







Job separation sheet

Casing S. <u>9 37</u> Csg.Perf.	<u> </u>	0 ∕ E Suc. ft . 180 Sx. Int	7 @ 36 	92 w 650	Sx. Pr. <u>4</u> Prod. Stim.	1/2 6	7 <u>528</u> -,	w_525_	Sx. T.			↑ Gas
.P	BO/D _MCF/D After	Hrs. SICP	PS	AfterD	Grav		1st De	I. Gas				A N S
	OPS	NITD χ		Well Log		TEST DAT						
Ojo Alamo		C · 103		Plat		Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104		Electric Log					1	 		K81.140.
Fruitland				C-122		 -			+	+	 	
Pictured Cliffs		Ditr		Dfo		 			 	 -		
Chacra		Datr		Doc					 	 		
Cliff House	4614		1 2 1	7-17-15					 	<u> </u>	ļ — —	
Menefee	4724	1							 	 -		
Point Lookout	5240	1				╟──┤			<u> </u>		ļ	
Mancos		1							 		<u> </u>	<u> </u>
Gallup						 				.		
Greenhorn	7168	1				 			 	 		ļ
Dakota	7332					 						
Entrada		-							ļ			
	 	-		Acres								

O Blanco PC Co. SJ s 29 1 29N R 8W UA Oper. Tennero Oil Company Lse. Hughes

No. 4

Formarily 9-331) CEPARTMENT OF THE BUREAU OF LAND MAN		5. LEASE DESIGNATION AND SERIAL NO. SF 078046				
SUNDRY NOTICES AND REF	PORTS ON WELLS	6. IF INDIAN, ALLOTTER OR TRIBE NAME				
1.		7. UNIT AGREEMENT NAME				
OIL GAR WELL OTHER 2. NAME OF OPERATOR		8. FARM OR LEASE NAME				
Tenneco Oil Company	Hughes					
S. ADDRESS OF OPERATOR	250511/53	9. WELL NO.				
P O Box 3249, Englewood , Colorado	80155 RECEIVED	4				
 LOCATION OF WELL (Report location clearly and in accordan See also space 17 below.) 		10. FIBLE AND POOL, OR WILDCAT Basin Dakota				
At surface	FEB 0 5 1987	11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA				
1020' FNL, 810' FEL		SURVEY OR AREA				
	BUREAU OF LAND MANAGEMENT	Sec. 29, T29N, R8W				
	FARMINGTON RESOURCE AREA w whether DF, BT, GR, etc.)	12. COUNTY OR PARISH 18. STATE				
30-045- 23492 6396 ' GL	·	San Juan NM				
16. Check Appropriate Box To	Indicate Nature of Notice, Report, or t	Other Data				
NOTICE OF INTENTION TO:		QUENT REPORT OF:				
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL				
FRACTURE TREAT MULTIPLE COMPLETE	PRACTURE TREATMENT	ALTERING CASING				
BHOOT OR ACIDIZE ABANDON®	SHOOTING OR ACIDIZING	ABANDONMENT [®]				
REPAIR WELL CHANGE PLANS	(Other) (Norm: Report result	as of multiple completion on Weil				
(Other) Withdraw request 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state)	pletion Report and Log form.)					
		RECEIVED				
		OIL CON. DIV.				
18. I bereby certies that the brogoth to the afti correct	TITLE Sr. Administrative Anal	yst _{DATE} 1/30/87				
Timothy & Foster	ALL ME.	VAID				
(This space for Federal or State office use)		- Armenten For Denigo				
APPROVED BY	TITLE	ACCEPTED FOR PERIOD				
Съ		ACCEPTED FOR 852279 -				
		PATE 06 1987				
or *c.	Instructions on Reverse Side					