Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED				
Budget Bureau No.	1004-0135			
Expires: March	11 1003			

				,	-
5.	Lease	Designation	and	Serial	No

6. If Indian, Allottee or Tribe Name

New Construction

Water Shut-Off

Dispose Water

Non-Routine Fracturing

Conversion to Injection

(Note: Report results of multiple completion on Well

5.	Lease	Designation	and	Serial	N
	SF-	-0763 % 7	7		

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
				~	*******

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

USB APPLICATION PO	R PERMIT— for such proposals	
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well Oit Well Well Other 2. Name of Operator		8. Well Name and No. Heath Gas Com D #1
Amoco Production Company A	9. API Well No.	
3. Address and Telephone No. P. O. Box 800 Denver, Colo 4. Location of Well (Footage, Sec., T., R., M., or Survey D		30-045-08546 10. Field and Pool, or Exploratory Area. Blanco Mesaverde
1850' FNL, 1650' FEL Sec. 8	3, T29N-R09W Unit "G"	11. County or Parish, State San Juan, NM
2. CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, I	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF A	CTION
Notice of Intent	Abandonment	Change of Plans

Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Recompletion

Plugging Back

Casing Repair

Altering Casing

See attachment for procedures.

Subsequent Report

Final Abandonment Notice

JUL 3 0 1992 OIL CON. DIV.

Bradenhead Repair

If you have any questions, please contact Julie Acevedo (303) 830-6003.

14. I hereby certify that the foregoing is true and correct		
14. I hereby certiff that the foregoing is true and correct Signed Amadom 93	Tide Sr. Staff Admin. Supv.	Date 7-23-22
(This space for Federal or State office use)		ACCEPTED FOR ILLOW
Approved by	Title	JPM 29 1992
Conditions of approval, if any:		300 20 1000
		FARMINGTON RESOURCE AREA

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unifed Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unifed Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unifed Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unifed Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unifed Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unifed Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unifed Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unifed Section 1001, makes it as a crime for any person knowingly and willfully to make to any department or agency of the Unifed Section 1001, makes it as a crime for any person knowingly and willfully to make to any department of the Unifed Section 1001, makes it as a crime for any person knowingly and will any department of the Unifed Section 1001, makes it as a crime for a c or representations as to any matter within its jurisdiction.

Heath Gas Com /D/ #1 3/17/92 - 3/21/92

MIRUSU. Kill well. NDWH. NUBOPS. PR TST blind & pipe rams to 3000psi. OK. TIH & tag fill @ 4564'. TOH W/ TBG & stand 147 jnts. Make up scraper & TIH to 3561'. TOH. Lay dwn scraper. PMP 60 BBLS 2% KCL WTR. Make up ret bridge plug. TIH W/ 2-3/8 TBG. Set plug @ 3502'. PR TST CSG to 1000psi. Ok. TOH. RI WLE. Run CBL-VDL-GR-CCL log from 2250' to surf. TIH & perf 2 holes @ 820'. RD WLE. Estab circ. Ok. Dump sand on top of plug. TIH W/ PKR & set @ 510'. Establ feed rate of 3 BPM. PMP 400 sxs oilwell + 2% CACL2. Obtained 9 BBLS good CMT returns. Rel PKR. TOH. TIH on 2.375 TBG. Tag CMT 621'. RU swivel. Break circ. DRL CMT to 834'. Circ hole clean. PR TST CSG to 500psi. OK. TOH. Lay dwn collars. Make up plug ret hd. TIH W/ 45 stds. continue in hole W/7" plug ret hd. Circ sand off plug. Rel same. TOH W/ plug. Run prod TBG. 2 3/8" TBG landed @ 4504'. NDBOPS. NUWH. RDMOSU.