

F

F. loc. 1690/N; 900/E Elev. 6047 DF Spd. 7-28-65 Comp. 8-18-65 TD 7245 PB 7216
Casing 10-3/4 @ 204 W 200 Sx. Int. 7 @ 4197 W 200 Sx. Pr. 4 1/2 @ 7245 W 200 Sx. T. 2 3/8 @ 6910
Csg. Perf. 1977-6980, 7086-7215 SWF
Prod. Stim.

1205 ACIF
I.P. 1196 BO/D MCF/D After 3 Hrs. SIEP 208 PSI After Days GOR Grav. 1st Del. 5-9-67

TOPS		NITD	X	Well Log	TEST DATA						
Kirtland		C-102		Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland		C-103		Electric Log	3/13/67	1231	134	237	916	109	#41
Pictured Cliffs		C-104 2 1/2		E-110 12-20-65	3/19/68	1342	60	246	671	50	
Cliff House	4270	7-10-67		C-122	10/18/69	1138	38	260	569	32	
Menefee	4450	Ditr 7-5-67		Dfa 5-9-67	6/4/70	1015	13	240	508	11	
Point Lookout	4855	Datr		Dac	6/24/71	1133	35	160	567	29	
Mancos	5020	Remarks E-320			6/26/72	1117	2	172	559	2	
Gallup					6/21/73	1374	7	152	687	6	
Sanostee					11/18/75	1004	22	123	502	18	XIV
Greenhorn					Discontinuity						
Dakota	1974				619/76						
Morrison											
Entrada											