

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer D10, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-045-27503
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-5226-1

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name  FC STATE COM
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		
2. Name of Operator Mesa Operating Limited Partnership		8. Well No. # 11
3. Address of Operator P.O. Box 2009, Amarillo, Texas 79189		9. Pool name or Wildcat Basin Fruitland Coal
4. Well Location Unit Letter <u>H</u> : <u>2220'</u> Feet From The <u>North</u> Line and <u>1045'</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>29N</u> Range <u>8W</u> NMPM San Juan County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6289' GR		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>OIL CON. DIV</u> <input type="checkbox"/>		OTHER: <u>Casing Test/Perf/Frac</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pressure tested tree and 5 1/2" casing to 5000 psi for 30 min. on June 11, 1990. OK. RU Western Co. & Blue Jet Perforators and per Fruitland Coal from 2879'-2934' w/4" casing gun, 4 SPF for a total of 68 holes. Frac'd w/32,800 gals 30# x-linked gel + 11,000# 40/70 sand, 65,400# 20/40 sand. ISIP 780 psig. Set Baker Model "T" CIBP @ 2865'; pressure tested to 5000 psig, OK. Perf'd Fruitland Coal from 2671'-2852' w/4" csg gun, 4 SPF for a total of 204 holes. Frac'd w/80,000 gals 30# x-link w/18,000# 40/70 sand, 216,000# 20/40 sand. ISIP 1270 psig.

cc: NMOCD-A (0+5), WF, Reg, Land, Expl., Drilling

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cathy McKee TITLE Regulatory Analyst DATE 6/13/90

TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT III DATE JUN 20 1990

CONDITIONS OF APPROVAL, IF ANY: