Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

District Office	Revised 1-1-89
DISTRICT OIL CONSERVATION DIVIS	ION WELL API NO.
P.O. Box 2088 DISTRICT II P.O. Drawer DD. Arlesia NM 88210 Santa Fe, New Mexico 87504-2088	
DISTRICT III	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No. SF 078132
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	K TO A 7. Lease Name or Unit Agreement Name
1. Type of Well: OIL OAS WELL X OTHER	Federal 29-9-10
2. Name of Operator Richmond Petroleum Inc. 3. Address of Operator	8. Well No. 1
P.O. Drawer2039, Farmington, NM 87499 4. Well Location	9. Pool name or Wildcat Basin Fruitland Coal
Unit Letter G: 1480 Feet From The North Line and	1270 Feet From The East Line
Section 10 Township 29 North Range 9 We	st NMPM San Juan
10. Elevation (Show whether DF, RKB, RT, GF	2, etc.)
//////////////////////////////////////	
11. Check Appropriate Box to Indicate Nature of No.	otice, Report, or Other Data
	otice, Report, or Other Data SUBSEQUENT REPORT OF:
Check Appropriate Box to Indicate Nature of No NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
Check Appropriate Box to Indicate Nature of Notice OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W	SUBSEQUENT REPORT OF:
Check Appropriate Box to Indicate Nature of Notice OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORKERPORARILY ABANDON CHANGE PLANS COMMENCE	SUBSEQUENT REPORT OF:
Check Appropriate Box to Indicate Nature of Notice OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WITH PLUG AND ABANDON COMMENCE CASING CASING TES	SUBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT
Check Appropriate Box to Indicate Nature of Notice OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WITH PROPRIATE ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING CASING TES	SUBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND CEMENT JOB X
Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORKER PLANS COMMENCE CASING TES PULL OR ALTER CASING CHANGE PLANS COMMENCE CASING TES OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent work) SEE RULE 1103. Spud well at 3:00 p.m. 10/27/90. Orilled 12-1/4" hole to 270' KB. Ran 6 jts of 8 5/8", Cemented casing with 220 sx (260 cf) of Class B cement. 1.4 #/sk cellophane flakes. Circulated 13 bbls of excellophane.	SUBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND CEMENT JOB X Lates, including estimated date of starting any proposed 23 #, LS, 84d, ST&C casing. c ontaining 2% CaCl and
Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORKED COMMENCE CASING TEST COMMENCE CASING TEST CASI	SUBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND CEMENT JOB X Lates, including estimated date of starting any proposed 23 #, LS, 84d, ST&C casing. c ontaining 2% CaCl and
Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORKER PLANS COMMENCE CASING TES PULL OR ALTER CASING CHANGE PLANS COMMENCE CASING TES OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent work) SEE RULE 1103. Spud well at 3:00 p.m. 10/27/90. Orilled 12-1/4" hole to 270' KB. Ran 6 jts of 8 5/8", Cemented casing with 220 sx (260 cf) of Class B cement 1./4 #/sk cellophane flakes. Circulated 13 bbls of excellophane	SUBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND CEMENT JOB X Lates, including estimated date of starting any proposed 23 #, LS, 84d, ST&C casing. containing 2% CaCl and ess cement to surface. Casing NOVI = 1990 OIL CON. DIV.
Check Appropriate Box to Indicate Nature of Non Notice of Intention to: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE CASING TES PULL OR ALTER CASING CASING CHEARLY State all periment details, and give pertinent of work) SEE RULE 1103. Spud well at 3:00 p.m. 10/27/90. Orilled 12-1/4" hole to 270' KB. Ran 6 jts of 8 5/8", Cemented casing with 220 sx (260 cf) of Class B cement 1/4 #/sk cellophane flakes. Circulated 13 bbls of excesset at 259' KB. Shut in casing and WOC.	SUBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND CEMENT JOB X Lates, including estimated date of starting any proposed 23 #, LS, 84d, ST&C casing. containing 2% CaCl and ess cement to surface. Casing NOVI : 1990 OIL CON. DIV. DIST. 3
Check Appropriate Box to Indicate Nature of Non Notice of Intention to: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE CASING TES PULL OR ALTER CASING CASING CHEARLY State all periment details, and give pertinent of work) SEE RULE 1103. Spud well at 3:00 p.m. 10/27/90. Orilled 12-1/4" hole to 270' KB. Ran 6 jts of 8 5/8", Cemented casing with 220 sx (260 cf) of Class B cement 1/4 #/sk cellophane flakes. Circulated 13 bbls of excesset at 259' KB. Shut in casing and WOC.	SUBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND CEMENT JOB X Lates, including estimated date of starting any proposed 23 #, LS, 84d, ST&C casing. containing 2% CaCl and ess cement to surface. Casing NOVI = 1990 OIL CON. DIV.