## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



	UREAU OF LAND MANAGEMENT	Ct. 1000 to the man-
Sund	ry Notices and Reports on W	ells and 10 All /: 59
1. Type of Well GAS  2. Name of Operator MERIDIAN OLL  3. Address & Phone No. of PO Box 4289, Farmington  4. Location of Well, Foota	MAR21 1994  OL CON. DIV.  Operator  on, NM 87499 (505) 326-9700	San Juan 30-6 Unit  8. Well Name & Number San Juan 30-6 U 61
12. CHECK APPROPRIATE BOX Type of Submission Notice of Intent x Subsequent Repor	Recompletion rt Plugging Back Casing Repair	Rio Arriba Co, NM CE, REPORT, OTHER DATA
03-08-94 MOL&RU. ND WH. Nl. Pull up to 5138'. Si 03-09-94 Ran GR-CBL-CCL 552 5175'. Ran GR-CB 5260'. Pump 1000 03-10-94 TOOH w/FBP. Set fra sand and 180,940s Dump 2 sx sand. F Set FBP @ 62'. 03-11-94 Frac Lewis w/20/40 san w/pressure bombs 03-12/15 Blow and CO.	Completed Operations  J BOP. TOOH w/tbg. Ran scraper to 5530'. Set pkr. PT 3000#/15 min, ok. TOOH. 20-4600'. Hole taking fluid. Dump sand on Ri BL-CCL 5175-3700'. TOC @ 3850'. TOOH w D gal acid Set pkr @ 5260'. Set pressure to c liner 5170-5270'. Set FBP @ 62'. PT 1000 # 20/40 sand and x-link gel. TOOH w/frac li Perf Lewis 4135-5073' w/23 holes. Set FBP ond and gel. Flow back after frac. Run presses. Unload well.  2 jts 2 3/8", 4.7#, J-55 8rd tbg landed @ 568	BP @ 5520'. TOOH w/RBP. Set RBP @ r/RBP. Perf 5308-5496'. Set FBP @ r/RBP. Perf 5308-5496'. Set FBP @ r/RBP. Perf 5308-5496'. Set FBP @ r/RBP. Set RBP @ 5308'. Set FBU. #, ok. Frac Menefee w/20,940# 40/70 ner. Set RBP @ 5150'. PT 3000#, ok. @ 62'. Spot 1500 gal acid. TOOH w/FBP ure bombs to 4050' and SI well. TOOH
Signed Many Certify that  Signed Many Many  (This space for Federal of APPROVED BY  CONDITION OF APPROVAL, if	r State Office use) Title	COTTECT.  AffaACCEPTED FORMECORD  MARLE B 1994  FARMINGTON DISTRICT OFFICE BY