Form	9-331	8
(Feb	. 1951)	



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	sente Pe	
Lease No.	472140	
Unit	san Juan 30-5 Uni	L

NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS. NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO REDRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE. NOTICE OF INTENTION TO PULL OR ALTER CASING. NOTICE OF INTENTION TO PULL OR ALTER CASING. NOTICE OF INTENTION TO ABANDON WELL NOTICE OF INTENTION TO ACIDIZE (Ner (Ne	F SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO REST WATER SHUT-OFF. NOTICE OF INTENTION TO REDRILL OR REPAIR WELL. NOTICE OF INTENTION TO SHOOT OR ACIDIZE. NOTICE OF INTENTION TO PULL OR ATER CASING. NOTICE OF INTENTION TO PULL OR ATER CASING. NOTICE OF INTENTION TO ABANDON WELL. (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR SUBSEQUENT REPORT OR SUBJECT OR SUBJECT OR SUBJECT OR SUBJECT OR	
Well No	
Well No. 3 is located 3 ft. from N line and	RE-DRILLING OR REPAIR SURVEY
Well No. 3-30 is located 350 ft. from N line and 350 in M. M. (W Sec. and Sec. No.) (Twp.) (Range) (Mer (Rang	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY FARMING TON.
Well No. 3 is located 3 ft. from N line and	HISTORY U.S. INGTONI
Well No. 3- % is located #% ft. from N line and #% is located #% ft. from N line and #% line and expected depths to objective sands; show sizes, weights, and lengths of proling points, and all other important proposed work for his points, and all other important proposed work for his points, and all other important proposed work following mainer: 1. Spot a li2' cement plug from 564-5052' to cover line for casing free point and cut. 3. If cut-off is telew 3202' spot a 100' cement plug line point and cut casing. 5. Spot a 100' cement plug across cut off, pull casi top of surface pipe. 7. Clean location. 1 understand that this plan of work must receive approval in writing by the Geological Surr Company & lass Natural Cas Company	- FAIO
MS/4 Section 36 (Twp.) (Range) (Mer (Range) (Mer (Range))	R OTHER DATA)
MS/4 Section 36 (Twp.) (Range) (Mer (Range) (Mer (Range))	(F)
Rio Arrita (Field) (County or Subdivision) The elevation of the derrick floor above sea level is DETAILS OF WORK State names of and expected depths to objective sands; show sizes, weights, and lengths of proing points, and all other important proposed work Due to non-connercial (as production this well will be the following manner: 1. Spot a 612' cement plus from 5664-5052' to cover 2. Determine 5" casing free point and cut. 3. If cut-off is telow 322' spot a 100' cement plus 4. Determine 5" casing free point and cut casing. 5. Spot a 100' cement plus across cut off, pull casi 6. Spot a 100' cement plus with a 4" x 4" personne top of surface pipe. 7. Clean location. I understand that this plan of work must receive approval in writing by the Geological Surv Company El 1850 Natural Gas Company	.».
The elevation of the derrick floor above sea level is	,
DETAILS OF WORK State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed work Due to non-connercial as production this well will be the following manner: 1. Spot a 112' cement plug from 5004-5052' to cover 2. Determine 5" casing free point and cut. 3. If cut-off is below 322' spot a 100' cement plug 4. Determine 5" casing free point and cut casing. 5. Spot a 100' cement plug across cut off, pull casi 6. Spot a 100' cement plug across cut off, pull casi 7. Clean location. I understand that this plan of work must receive approval in writing by the Geological Surv Company 21 Paso Natural Cas Company	(State or Territory)
I understand that this plan of work must receive approval in writing by the Geological Surv Company El 1880 Satural Cas Company	plugged à shendoned in perforations 5614-5102'. across out-off. Full Cast
Company El Paso Natural Cas Company	
•	
Address Box 930	ey before operations may be commenced.
nuuress	ey before operations have be commenced.
Farsington, New Mexico By	ey before operations hydy be commenced.