UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports o	nu c c c	
	5.	Lease Number
1. Type of Well GAS	CO A 6.	SF-080712A If Indian, All. of Tribe Name
2. Name of Operator	7.	Unit Agreement Na
BURLINGTON RESOURCES OIL & GAS COMPANY		San Juan 30-6 Uni
3. Address & Phone No. of Operator	8.	Well Name & Numbe San Juan 30-6 U :
PO Box 4289, Farmington, NM 87499 (505) 326-	9700 9. - 	API Well No. 30-039-07805
4. Location of Well, Footage, Sec., T, R, M 1650'FNL, 1180'FEL, Sec. 21, T-30-N, R-6-W, NMP	M	Field and Pool Blanco Mesaverde County and State Rio Arriba Co, NA
X Other - Tubir 13. Describe Proposed or Completed Operations	ng repair	
8-25-97 MIRU. ND WH. NU BOP. TIH, tag up. To csg scraper to 3537'. TOOH. SDON. 8-26-97 TIH w/5 1/2" csg scraper to 5754'. Load hole w/205 bbl wtr. Roll hole tool. Latch RBP,	TOOH. TIH w/5 1/2" I Le. PT csg to 525 psi TOOH. SDON.	RBP, set @ 5215'. i/15 min, OK. TOOH.
8-27-97 TIH, blow well & CO. TOOH. TIH w/18 @ 5717'. ND BOP. NU WH. Blow well 8-28-97 RD. Rig released.	33 jts 2 3/8" 4.7# J-	-55 EUE tbg, landed
	Dickson Via ser	
	yashin ya Malausi in	
igned Juffy Mannueld Title Regulator		e 8/29/97
This space for Federal or State Office use) PPROVED BY Title		ED FOR RECOKE
ONDITION OF APPROVAL, if any:	91	FP 0 4 1997