

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 080713-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

PO Box 990, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

990'N, 930'E

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Barron Kidd

9. WELL NO.

1-B (P&A)

10. FIELD AND POOL, OR WILDCAT

Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 22, T-30-N, R-6-W
NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6517'GL

12. COUNTY OR PARISH

13. STATE

Rio Arriba

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The subject well was temporarily plugged and abandoned from 1-18 to 1-21-63 in the following manner:

Spotted a 100 sk. cement plug across the open hole section (5265-5790').

It was permanently plugged and abandoned from 11-29- to 12-15-72 in the following manner:

Ran tubing, tagged old cement at 4678' and spotted a 25 sk. cement plug.

Perforated squeeze holes opposite the Pictured Cliffs formation at 3452'.

Spotted a 50 sk. cement plug and squeezed 30 sks. through perfs.

Perforated squeeze holes opposite the Ojo Alamo formation at 2670'.

Spotted a 50 sk. cement plug and squeeze 30 sks. through perfs.

Perforated squeeze holes at 1500'. Spotted 200 sks. of cement, squeezed 100 sks. through perfs.

Pumped 100 sks. of cement down the bradenhead.

Installed dry hole marker with a 15 sk. cement plug.

Note: an additional subsequent report will be filed after the location has been cleaned and leveled.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Petroleum Engineer

DATE January 15, 1973

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OIL CON. COM.

DIST. 3

JAN 16 1973