(SUBMIT IN TRIPLICATE)

and	Office	San ta	Fe

Lease No. 079001-

Unit Bortheast Blanco

UNITED STATES DEPARTMENT OF THE INTERIOR Unit Agreement No. 1. Sec. 929

GEOLOGICAL SURVEY

LEMMITTAL

	Olices An	ID REPOR	TS ON WEL	LS
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPO	RT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		11	RT OF SHOOTING OR ACIDIZ	
NOTICE OF INTENTION TO TEST WATER S	!		RT OF ALTERING CASING	
IOTICE OF INTENTION TO		SUBSEQUENT REPO	RT OF RE-DRILLING OR REP	AIR
NOTICE OF INTENTION TO SHOOT OR ACI	!	SUBSEQUENT REPO	RT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTE	1	H	ELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	i i			
(INDICATE A	BOVE BY CHECK MARK N	ATURE OF REPORT, NOT	ICE, OR OTHER DATA)	
		·	March 28	, 19. 58
		$\left\{S\right\}$ line and	ft. from W li	ne of sec. 10
sv/4 Sec. 10	(Twp.) (E	(ange)	(Meridian)	
(1/4 Sec. and Sec. No.)	(Twp.) (2		Now Marris	
lanco Heneveres (Field)		Subdivision)	(State or Ter	ritory)
	jective sands; show sizes ing points, and all oth			
ull 2-3/8" tubing, cles 90' of 5%" liner (with cleatively perforate ti	jective sands; show sizes ing points, and all oth in out with gas turned down or	, weights, and lengths her important proposes to approximalized, and pliants), and roup and sand	ately 5530°, re coment with 350 -water free in	approximatel sacks consid-
ull 2-3/8° taking, close of 50° liner (with colorate the colorate the colorate the color gallens of water corum taking and repotent	jective sands; show sizes ing points, and all other out with gas turned down on Hossaverie 2 and 50,000 lb	, weights, and lengths her important proposes to approximalized, and pliants), and roup and sand	stely 5530°, recommend with 350 -water free in congress of the	approximately and a stage of the stage of th
Tunderstand that this plan of work means to be seen to	jective sands; show sizes ing points, and all of the out with gas turned down of	writing by the Geologic	estaly 5530°, recement with 350 -water free in retage.	APRI 1958
I understand that this plan of work memory Jackwood & Micon Memory Jackwood & Micon	jective sands; show sizes ing points, and all of the out with gas turned down of	writing by the Geologic	estaly 5530°, recement with 350 -water free in r stage.	APRI 1958
I understand that this plan of work means to be seen to	jective sands; show sizes ing points, and all oit in out with gas turned down on himself down of and 50,000 lbs.	writing by the Geologic (Unit Operate	estaly 5530°, recement with 350 -water free in retage.	APR 1958

