



(SUBMIT IN TRIPLICATE)

 UNITED STATES  
 DEPARTMENT OF THE INTERIOR  
 GEOLOGICAL SURVEY
Land Office Santa FeLease No. 079001Unit Northeast Blanco

Unit Agreement No. 1, Sec. 29

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF <del>RE-DRILLING</del> OR REPAIR	<b>X</b>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

WORKOVERJune 25, 1958Well No. 8-10 is located 1650 ft. from N line and 1650 ft. from W line of sec. 10S<sup>1</sup>/<sub>4</sub> Section 10  
( $\frac{1}{4}$  Sec. and Sec. No.)30N  
(Twp.)7W  
(Range)NMPM  
(Meridian)Blanco Mesaverde  
(Field)Rio Arriba  
(County or Subdivision)New Mexico  
(State or Territory)The elevation of the derrick floor above sea level is 6273 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Original TD 5530'. On 5/22/58, pulled tubing thru bridges & found hole dry. Cleaned out to TD and on 5/25/58, ran 17 Jts 5 $\frac{1}{2}$ " 15.50# J55 casing as liner - 701' set at 5529' and hung at 4828' with Burns plain hanger. Cemented with 200 sacks 4% gel cement with  $\frac{1}{2}$  lb floccs per sack. Squeezed top of liner with 100 sacks regular cement to 2500 P.I. Pressure would not hold. Found holes in 7" casing 486'-755' and on 5/26/58, stage squeezed holes in casing with 250 sacks regular cement. Tested 7" casing with 1000 P.I for 30 minutes. Held OK. Cement plug back depth: 5509'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BLACKWOOD & NICHOL COMPANY (WELL OPERATOR)Address P.O. Box 1237  
Darango, ColoradoOriginal Signed  
By DeLasso Loos DeLasso LoosTitle Field Superintendent