

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-015  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals.

1. ☐ Oil Well ☒ Gas Well ☐ Other

2. Phillips Petroleum Company

3. 5525 Hwy. 64, NBU 3004, Farmington, NM 87401 (505) 599-3454

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit B, 1100' FML & 1500' FEL  
Section 11, T-30-N, R-5-W

5. Lease Designation and Serial Number

ST-080538

6. If Indian, Allottee or Tribe Name

FARMINGTON, NM

7. If Unit or CA, Agreement Designation

SAN JUAN 30-5 UNIT

8. Well Name and No.

SAN JUAN 30-5 UNIT #8

9. API Well No.

30-039-07898

10. Field and Pool, or Exploratory Area

BLANCO MESAVERDE

11. County or Parish, State

RIO ARriba, NEW MEXICO

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input checked="" type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other _____	<input type="checkbox"/> Dispose Water

(Note Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimate date of starting any proposed work. If well is directionally drilled, give subsurface locations and true vertical depths for all markers and zones pertinent to this work.)\*

(Plans were submitted to TA this well, but were changed to P&A).

Well will be abandoned in the following manner:

- Set CIBP @ 5800', spot 50' Class B cement on top of bridge plug.
- Since it was determined that there was communications with bradenhead and the leak has been isolated @ 1257', plans are to spot 46 sx Class B cement from 5793' to 5554' across Mesa Verde formation. Spot 27 sxs cement from 3536' - 3393' across PC formation. Spot 106 sx from 3231' to 2670' across Fruitland Coal, Ojo & Nacimiento formations together.
- Shoot 4 squeeze holes @ 1335' and spot 62 sx cement (37 sxs outside and 25 sxs inside the 7" casing) from 1562' to 1362'.
- Pump 300 sx Class B cement up through retainer and established circulation up through bradenhead. Close bradenhead valve. and spot 11 sxs on top of retainer.
- Circulate 40 bbls packer fluid (55 gals WA 5810 per 100 bbls fresh water). (This was approved by Ken Townsend & Steve Mason @ 8:30 am 6-2-94.)
- Pump 46 sxs cement to spot surface plug. Top of cement in wellbore.
- Cut off casing, cap, place abandonment marker, and restore location.

All of the above, except the surface restoration, has been done. This is an after the fact Notice of Intent. All procedures performed were verbally approved by Ken Townsend or Steve Mason. No surface rehabilitation will take place until the BLM stipulations have been received.

14. I hereby certify that the foregoing is true and correct.

Signed Ed Hasely Ed Hasely Title Environmental/Regulatory Engineer Date June 9, 1994

(This space for Federal or State office use)

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_  
Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

NM000

APPROVED  
JUN 10 1994  
DISTRICT MANAGER