UNITED STATES DEPARTM

SUBMIT IN TRIPLICATE.

Form approved.

		Duuget						
٠	LEASE	DESIGNA	MON	AND	굹	RIAL	NO.	•
				_				

IENT OF THE INTERIOR	verse side)	on	re-	5. LE
EOLOGICAL SURVEY				

GEOLOGICAL SURVEY	NM 4454
SUNDRY NOTICES AND REPORTS ON WELLS (The not use this form for proposals to drill or to deepen or plug back to a different reservoir Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IP INDIAN, ALLOTTER OR TRIBE NAME
	7
WELL STREET OTHER	7. UNIT AGREEMENT NAME
2 NAME OF OPERATOR	4
LONE STAR INDUSTRIES, INC.	FARM OR LEASE NAME
3 ADDRESS OF OPERATOR % JOHN E. SCHALK	SCHALK 54
P. O. BOX 2078, FARMINGTON, NEW MEXICO \87401	A T T T T T T T T T T T T T T T T T T T
See also space 17 below.)	10. PIELD AND POOL, OR WILDCAT
At surface	
1650' FROM THE SOUTH LINE, 790' FROM THE EAST LIN	BLANCO MESA VERDE 11. and, 11. and, or silk. AND
SECTION 2, TOWNSHIP 30 NORTH, RANGE 5 WEST	SURVEY OR ARMA
	SEC. 2, T-30N, R-5W
17. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 18. STATE
6569' GR	RIO ARRIBA NEW MEXICO
6. Check Appropriate Box To Indicate Nature of Notice, Report	
	, or Other Data
NOTICE OF INTENTION TO .	UBSEQUENT REPORT OF:
TEST WATER SHIT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
SHOOT 4 OHZE ABANDON* SHOOTING OR ACIDIZIN	IG ABANDONMENT*
CHANGE PLANS (Other) WE	
Completion or R	results of multiple completion on Well ecompletion Report and Log form.)
processes work. If well is directionally drilled, give subsurface locations and measured and true nent to this work.)*	
SCHALK 54 NO. 2 WELL SPUDDED AT 5:00 PM ON 7-	09-74
7-10-74 TD 310'	
RAN 7 JOINTS OF 8-5/8" 32# CASING TOTALING	295'. SET AT 308'KB
CEMENTED WITH 250 SACKS, CLASS "B", WITH 1/	4# FLOSFAL PER SACK
WITH 2% CALCUIM CHLORIDE. PLUD DOWN AT 7:1	5 AM ON 7-10-74.
7-26-74 TD 5957'	
RAN 179 JOINTS OF 4-1/2" CASING TOTALING 59	79.97 SET AT 5957'.
CEMENTED 1ST STAGE WITH 160 SACKS 65/35 POS	MIX WITH 12-1/2#
GILSONITE AND 6% GEL PER SACK AND 160 SACKS	50/50 POSMIX WITH
2% GEL AND 12-1/2# GELSONITE PER SACK. CEM	ENTED 2ND STAGE WITH
690 SACKS 65/35 POSMIX WITH 12% GEN AND 12-	1/2# GELSONITE AND
1/4# FLOSEAL. PLUG DOWN AT 9:45 AM ON 7-26	-74.
PERFORATIONS:	
5636' - 5650' 3 HOLES 5812' -	5856' 44 HOLES
	JOJU 44 MULES
5692' - 5709' 3 HOLES hereto cardly that the foregoing is true and correct	Control of the Contro
SINED TITLE AGENT	
The Trouble	DATE
APPRIATED BY CONDITIONS OF APPRICAL, IF ANY	DE DATE NO STATE

*See Instructions on Reverse Side