Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

- wrrice

Sum

5. Lease Serial No

SUNDRY NOTICES AND REPORTS	ON WELLS SF-078739
Do not use this form for proposals to drill or	to re-enter an  6. If Indian, Allottee or Tribe Name
abandoned well. Use Form 3160-3 (APD) for	such ptoposals.
SUBMIT IN TRIPLICATE - Other instruction	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well	San Juan 30-5 Unit
Oil Well X Gas Well Other	8. Well Name and No.
2. Name of Operator Phillips Petroleum Company SJ 30-5 Unit #56 9. API Well No.	
3a. Address 3b. Phone No. (include area code) 30-039-21294	
5525 Highway 64, NBU 3004, Farmington, NM 87401 505-599-3454 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Blanco Mesaverde
Unit M, 820' FSL & 860' FWL Section 22, T30N, R5W	11. County or Parish, State
Section 22, 130N, NSW	Rio Arriba, NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intent Acidize	Deepen Production (Start/Resume) Water Shut-Off
Alter Casing	Fracture Treat Reclamation Well Integrity
Subsequent Report Casing Repair	New Construction Recomplete X Other Add
Change Plans	Plug and Abandon Temporarily Abandon additional pay to
Final Abandonment Notice	
	details, including estimated starting date of any proposed work and approximate duration thereof.
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)  10/29/00. MIRU Key #19. Kill well w/water. ND WH & NU BOP. PT-0K. Pulled hanger & COOH w/tubing. RIH w/CIBP & set @ 4800'. Load hole & PT CIBP & casing to 500 psi - 30 minutes. Good test. COOH. RU Blue Jet & ran CBL from 4866' to 1400' TOC on 4-1/2" casing @ 3552' (liner top). & on 7" @ 2340'. Perforated Lewis Shale interval @ 1 spf .36" holes as follows:  4630'-32': 4577'-79': 4568'-70': 4524'-26'; 4510'-12': 4501'-03': 4297'-99': 4284'-86': 4263'-65': 4248'-50': 4228'-30'; 4019'-21' Total 36 holes.  RIH w/big bore packer & set @ 4547' (inside liner). Broke down perfs w/2% KCL. Released packer & reset packer @ 3800'. Acidized perfs w/24 bbls 15% HCl & ballsealers. Released packer & knocked balls off. COOH w/packer. RIH w/big bore packer & set @ 3602'. PT - 0K. Frac'd Lewis Shale w/200.040 # 20/40 sand & 60 Quality foam. ATP - 2480 psi, ATR - 45.2 bpm. ISDP-550 psi. Flowed back on 1/4" and 1/2" chokes. Released packer & RD flowback equipment. RIH w/3-7/8" bit & cleaned out fill to CIBP @ 4867'. Drilled out CIBP & C/0 to PBTD @ 5749'. PU & landed 2-3/8" tubing @ 5687' with "F" nipple set @ 5718'. ND BOP & NU WH. Pumped off check and RD & released rig 11/13/00. Turned well over to production to return to production.	
14. I hereby certify that the foregoing is true and correct Name (Pintal (Typed)	Title
Patsy Clugst	on Sr. Regulatory/Proration Clerk
A titas (lunton	Date 11/13/00
THIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved by	Title Date
Conditions of approval, if any, are attached. Approval of this notice does recrtify that the applicant holds legal or equitable title to those rights in the	ot warrant or subject lease Office
which would entitle the applicant to conduct operations thereon.  Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a	crime for any person knowingly and willfully to make to any Wartinen of the Unite
States any false, fictitious or fraudulent statements or representations as to any matter	er within its jurisdiction.