

## NEW MEXICO ENERGI, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION ONVISION
ACTED DISTRICT OFFICE
1000 RIA DORADO
ACTED INIL 67410
(000) SEL-6170 FAU: (000) SEL-6170
MILITARIO INIL 6800 INI-61401c.)

This form is not to be used for reporting packer lealings tests in Southeast New Mexico

Page 1 Revised 11/16/98

## NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

erator_Phil	lips Petroleu	un Co. 01765	4_Loas	e Nam	e San Ju	ian 30	)-5 Unit		Well No 12A
cation of W	/ell:Unit Letter_	ESec	<u>31'</u> Tw	p_30N	_Rge_ <sup>5W</sup> _	API	<b># 30-0</b> 39-22	2729	
	NAME OF RESERVOIR OR POOL			TYPE OF PROD. (Oil or Gas)			METHOD OF PROD. (Flow or Art, Lift)		PROD.MEDIUM (Tbg. or Csg.)
Upper Completion	Pictured Cli	ffs	gas		ıs	flowing			tubing
Lower Completion	Mesaverde			gas		flowing			tubing
		DDE	EI OW 9	ALTINA	I DRESSUI	RE DAT	ΓΔ		
Upper Completion	Hour, date shut-in		Leng	OW SHUT-IN PRESS! Length of time shut-in		SI press, Psig		s	tabilized? (Yes or No)
Lower Completion	Hour, date shut-in		Leng	Length of time shut-in		SI press. Psig		s	tabilized? (Yes or No
Completion			FI	LOW TE	ST NO.1				
Commenced et (1	hour, dete)*				Zone product	ng (Upper	or Lower):		
TIME (hour,date)	LAPSED TIME	PRESSURE				P.		REMARKS	
	SINCE*	Upper Completion Low		wer Completion					
							18.08.08.08.08.08.08.08.08.08.08.08.08.08		
							- 15/2 -	4	` <u>`</u>
							No	V 2001	
		<del></del>			1		(A) (B) (B) (B) (B) (B) (B) (B) (B) (B) (B		O I
							(PIL)	A P	
	-to during toot		<u> </u>		1				
	ate during test		_		51 t- '-				. GOR
Oil:							_Hours		
Gas:		MC	FPD; Te	ested thr	u (Orifice o	r Meter	):		
		MI	D-TEST	SHUT-	IN PRESSU	JRE DA	ATA		
Upper Completion	Hour, data shut-in			Length of time shut-in		SI press pelg			Stabilized? (Yes or
Lower Completion	Hour, date shut-in			Length of time shut-in			SI press. psig		Stabilized? (Yes or I

(Continue on reverse side)

mmenced at (hour, d	ele)** 11-15	-01		Zone producing (Upper or Lower):				
TIME (hour, dete)	LAPSED TIME SINCE **	Upper Completion	Lower Completion	PROD. ZONE TEMP.	REMARKS			
· · · · · · · · · · · · · · · · · · ·		75#	320					
		75#	50#		blew MN DN to 507			
duction rate d								
					Grav GOR			
narks:		MCI		Office of Meter).				
ereby certify th	nat the information	on herein containe	ed is true and con	aplete to the best	of my knowledge.			
proved 11	15/01 il Conservation D	· · · ·	19 O <sub>j</sub>	perator Ph	Oliss Petroloum			
vew Mexico O	II Conservation L	vivision	Ву	Jum	Kennedez			
Kruc	i Mouth	<b>-</b> ,	ті	de Tre	ld Toster			
Tours		^			<del>u-/wut</del>			

## NORTHWEST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

- 1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disrurbed. Tests shall also be taken at any time that communication is suspected or when requested by the Division.
- 2. At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Division in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3 The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- 5. Following completion of Flow Test No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.
- 6. Flow Test'No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedute for Flow Test No. 2 is to be the same as for Flow Test No. 1 except

- that the previously produced zone shall remain shut-in while the zone which was previouly shut-in is produced.
- 7. Pressures for gas-zone tests must be measured on each zone with a deadweigh pressure gauge at time intervals as follows: 3 hours tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and a hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midwapoint) and immediately prior to the conclusion of each flow period. Other pressures mabe taken as desired, or may be requested on wells which have previously shown questionable test data.

24-hour oil zone tests: all pressures, throughout the entire test, shall be continuous: measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as require above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexic Oil Conservation Division on Northwest New Mexico Packer Leakage Test Form Revise-10-01-78 with all deadweight pressures indicated thereon as well as the flowin temperatures (gas zones only) and gravity and GOR (oil zones only).