

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER ☒ Exploratory Well - P&A
2. NAME OF OPERATOR
Union Oil Company of California
3. ADDRESS OF OPERATOR
P. O. Box 2620 - Casper, WY 82602-2620
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
2300' FSL & 1875' FEL (NE NW SE)
14. PERMIT NO.
API No. 30-039-23905
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
8204' GR (Ungraded)

5. LEASE DESIGNATION AND SERIAL NO.
Jicarilla Contract #473
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Jicarilla (J21)
9. WELL NO.
1
10. FIELD AND POOL, OR WILDCAT
Wildcat Niobrara
11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA
Sec. 21, T.30N., R.1W.
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

4230' TD; 4178' ETD
13-3/8" @ 417' w/550 sx cmt
8-5/8" @ 3294' w/910 sx cmt
5-1/2" L from 2963-4228' w/280 sx cmt

Drilled in 1986.
Perforated Niobrara formation
w/1 spf w/3-3/8" select-fire
gun (48 holes) from 3576-4034'

Plugged and Abandoned Subject Well as Follows:

Ran 4.5" gauge ring to 4050'. Ran and set 5-1/2" EZ-Drill cement retainer on wireline to 3470'. TIH with stinger on 2-7/8" tubing and stung into retainer. Loaded annulus with 32 bbls. mud. Pumped 75 sacks of cement with 1/4#/sack flocele, mixed at 15.6#/gal. (yield 1.18 cu. ft./sx) from 4034' to 3470' at 4 bpm at 0-200-50-400 psi (Plug No. 1). Stung out of retainer and dumped 15 sacks of cement from 3470' to 3450'. Displaced with mud laden fluid. Spotted 70 sacks of cement from 3050' to 2850' (Plug No. 2). Spotted 35 sacks of cement from 2200' to 2100' (Plug No. 3). Spotted 35 sacks of cement from 475' to 370' (Plug No. 4). Spotted 20 sacks of cement from 50' to surface (Plug No. 5). POOH. N.D. BOP and casing head. Welded plate on 13-3/8" casing. Installed dry hole marker. Released rig on 5-21-87. Well plugged and abandoned on 5-21-87.

Note: A sundry notice will be submitted as soon as the location is cleaned up and ready for final inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED R. G. Ladd, Jr.

TITLE District Drilling Supt.

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

APPROVED
DATE 8-2-87

DATE 08-08-1987