Form 3160-5 (JUNE 1990)

UNI DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ITED STATES	FO
NT OF THE INTERIOR	

RM APPROVED

Budget	Bureau No.	1004-0135

Budget	Bureau	No.	1004-0135
_			

SUNDRY NOTICES AND REPORTS Do not use this form for proposals to drill or to deepen for re Use "APPLICATION FOR PERMIT" for su	entry to a different reservoir	I : JIC464
Use "APPLICATION FOR PERMIT" for su	(Tit) to a amoratic reservoir.	6. If Indian, Allotte or Tribe Name
	ICH PROPOSAIS DUBLIENUUER	UU Jicarilla Apache
SUBMIT IN TRIPLICATE	EUMOLINGON	7. If Unit or CA, Agreement Designation
1. Type of Well		II off on, Agreement Designation
Oil Well X Gas Well Other:		N/A
2. Name of Operator Mallon Oil Company		8. Well Name and No. Jicarilla 464 No. 2
P.O. Box 3256, Carlsbad, NM 88220	(505) 885-4596	9. Well API No. 30-039-24158
Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area E. Blanco, Pictured Cliffs
990' FNL and 790' FWL (NW NW) Unit D Sec. 32, T30N-R3W		11. County or Parish, State
OUE OV A DOD O DO VATE DO VIVO DO VIVO		Rio Arriba County, New Mexico
CHECK APPROPRIATE BOX(S) TO INDICAT	E NATURE OF NOTICE, REP	PORT, OR OTHER DATA
TYPE OF SUBMISSION		OF ACTION
X Notice of Intent	- Abandonment	Change of Plans
	X Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
*	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other:	Dispose Water
		(Note: Report results of multiple completion on Well
3736' 3830' and 3077' 4044'. One hale second of the	o isolate the Pictured Clif	fs perfs
3736'-3830' and 3977'-4014'. Open hole complete the 3705'. Initiate Fruitland Coal production.	to isolate the Pictured Clife Fruitland Coal formation	fs perfs from 3670'-
3736'-3830' and 3977'-4014'. Open hole complete the	to isolate the Pictured Clife Fruitland Coal formation	from 3670- 同臣CELVEA
3736'-3830' and 3977'-4014'. Open hole complete the 3705'. Initiate Fruitland Coal production.	to isolate the Pictured Clife Fruitland Coal formation	from 3670- 同臣CELVEA
3736'-3830' and 3977'-4014'. Open hole complete the 3705'. Initiate Fruitland Coal production. 1 I hereby certify that the foregoing is true and correct figned	Fruitland Coal formation	From 3670"- DIEGELVEN AUG 11737 OUL CONL. DUV.
3736'-3830' and 3977'-4014'. Open hole complete the 3705'. Initiate Fruitland Coal production. 1 I hereby certify that the foregoing is true and correct igned	e Fruitland Coal formation Office Manager Chief, Lands and Mi	From 3670"- FORE CELLY EN AUG 1 1 1001 OUL COILS DUVS Date 40497
3736'-3830' and 3977'-4014'. Open hole complete the 3705'. Initiate Fruitland Coal production. 1. I hereby certify that the foregoing is true and correct igned	the Office Manager Chief, Lands and Mi	From 36707- DIE CELVE AUG 11331 OIL GONO DIVO Date 4-24-97 Ineral Resources AUG 5 199