Form 3160-5 (November 1983) (Formerly 9-331)	bor 1983) Other Instructions on re-			Budget Burer Expires Augu 3. LEASE BESIGNATE	Form approved. Bedget Bureau No. 1004—0135 Expires August 31, 1985 3. LEASE DESIGNATION AND SERIAL NO. Jicarilla Contract 458	
(De not use this f	ORY NOTICES AND	REPORTS C	ON WELLS	G. IF INDIAN, ALLOT	THE OR TRIBE NAME	
[.					Jicarilla Apache Tribe 7. UNIT MESSMENT NAME	
2. NAME OF UPERATOR	OT#188		<u></u>	S. PARM OR LEASE I	AME	
Robert L. Bayless				Jicarilla	Jicarilla 458	
3. ADDRESS OF OFSEATOR	•			9. WELL NO.		
P.O. Box 168, Farmington, NM 87499				3	.	
4. LUCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1815' FNL & 230' FEL					10. FIELD AND POOL, OR WILDCAT	
					Wildcat 11. SEC. T. S. M., OR BLE. AND SCRYST OR AREA	
				Section 7,	T30N, R3W	
4. PERMIT NO. 15. BLEVATIONS (Show whether DF, RT, GR, etc.)		NT. GR. etc.)	12. COUNTY OR PARI	1		
		089'GL 71	.07' RKB	Rio Arriba	NM	
d.	• • •	x To Indicate No	ature of Natice, Report, a			
No	FICE OF INTENTION TO:		2010	EQUENT REPORT OF:		
TEST WATER SECT-OFF	PULL OR ALTER	- VS1NO	WATER SECT-OFF	BEPAIRING	WELL	
PRICTUSE TREAT	MULTIPLE COMP	ETE	PRACTURE TREATMENT	ALTERING		
SHOOT OR ACIDIZE	ABANDON*		SECOTING OR ACIDIZING	ABANDONY	ENT.	
(Other)	PAIR WELL CHANGE PLANS (Other) Soud not (Nors: Report results			its of multiple completion	of multiple completion on Well letton Report and Log form.)	
SEE ATTACE	HED DAILY REPORT.					
				MAR: OIL CO	EIVE 2 3 1988 DN. DIV. 51. 3	
SIGNED Kevin H. (This space for Federal	oregoing is true and correct. MGQul McCord or State office use;		Petroleum Engineer	DAT9	3/8/88	

*See Instructions on Reverse Side

ROBERT L. BAYLESS

PETROLEUM PLAZA BUILDING
P. O. BOX 168
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

JICARILLA 458 #3 Section 7, T30N, R3W 1815' FNL & 230' FEL Rio Arriba County, New Mexico

DAILY REPORT

3/08/88 Spud well at 4:00 PM on 3/7/88. Drilled 148 ft. of 9 7/8" surface hole. Ran 3 jts. (130.14 ft.) of 7 5/8" 26.4#/ft S-95 LTC used casing and landed at 143 ft. RKB. Rigged up Cementers, Inc. Cemented surface casing with 75 sacks (89 ft.3) of Class B cement with 3% CaCl2. Good circulation throughout job. Circulated cement to the surface. Wait on cement.