## UNITED STATES

BUREAU OF LAND MANAGEMENT RECEIVED	
Sundry Notices and Reports on Wells ROUM	
1. Type of Well 970 FARMUTON, NM	<ul> <li>5. Lease Number</li> <li>SF-080714A NM-06283</li> <li>6. If Indian, All. or</li> <li>Tribe Name</li> </ul>
	7. Unit Agreement Name
2. Name of Operator MERIDIAN OIL  3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	San Juan 30-6 Unit  8. Well Name & Number San Juan 30-6 U #433  9. API Well No.
4. Location of Well, Footage, Sec., T, R, M 1820'FSL, 1175'FWL, Sec.11, T-30-N, R-6-W, NMPM	30-039-24241  10. Field and Pool  Basin Fruitland Coal  11. County and State  Rio Arriba Co, NM
Recompletion New Con	of Plans struction tine Fracturing hut off
It is intended to move the central tank battery to the sub the San Juan 30-6 Unit #439 located in Section 14,	ject location from T-30-N, R-6-W.  EGETVE  JUN 1 3 1996
14. I hereby certify that the foregoing is true and correct.  Signed Malfuld Title Regulatory Administrato  (This space for Federal or State Office use)	Dist. w

DISTR MANAGER