First 3460-5 (** 'vember 1983) (Formerly 9-331)	UNITED ST DEPARTMENT OF T BUREAU OF LAND	HE INTER	SI'BMIT IN TRIPLICAT (Other instructions on verse side)	5, LEASE DESIGNATION AND SERIAL NO.	
	DRY NOTICES AND	REPORTS (ON WELLS	Jicarilla Contract 459 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	Use "APPLICATION FOR PER. X OTHER	Jicarilla Apache Tribe			
. NAME OF OPERATOR				8. FARM OR LEASE NAME	
Robert L. Rayless				Jicarilla 459	
. ADDRESS OF OPERATOR				9. WBLL NO.	
. LOCATION OF WELL (Re See also space 17 belo	58, Farmington, NM port location clearly and in account ' FNL & 1850' FEL	87499 ordance with any	State requirements.*	4 10. FIELD AND POOL, OR WILDCAT East Blanco P.C. 11. SEC., T., E., M., OR BLK. AND BURNET OR ARMA	
PERMIT NO 15 ELEVATIONS (Show whether DF, RT, GR, etc.)			Section 19, T30N, R3W 12. COUNTY OR PARISH! 13. STATE		
	7143 ' GL 7155 ' RKB				
			···	Rio Arriba NM	
d .	Check Appropriate Box	lo Indicate N	lature of Notice. Report, or	Other Data	
No	OTICE OF INTENTION TO:		SCBSI	EQUENT REPORT OF:	
TEST WATER SHUT-OF	PULL OR ALTER CA	SING	WATER SHUT-OFF	REPAIRING WELL	
FRACTUBE TREAT	MALTIPLE COMP: E		FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT®	
REPAIR WALL	CHANGE PLANS	1	(Other) Cement	longstring X	
(Other)			(Nors: Report result	its of multiple completion on Well apletion Report and Log form.)	
				DECATE I	
SIGNED KEVIN I (This space for Federa	n fl. M. Youl	TITLE P	etroleum Engineer	DATE11/4/88	
ADDDONOS CO					
CONDITIONS OF APP	ROVAL, IF ANY:	TITLE	Market Control	- ™ ATECEPTED FOR RECO RI NOV 0 8 1988	
	* Se	e Instructions	on Reverse Side	FARMINGTON RESOURCE AREA	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ROBERT L. BAYLESS

PETROLEUM PLAZA BUILDING
P. O. BOX 168
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

JICARILLA 459 #4
Section 19, T30N, R3W
790' FNL & 1850' FEL
Rio Arriba County, New Mexico

DAILY REPORT

10/29/88	Spud well at 5:30 PM on 10/28/88. Drilled 138' of 12 1/4"
	surface hole. Ran 3 its. of 8 5/8" 24#/ft J-55 casing
	(122.52 ft.) and landed at 135 RKB. Rigged up Cementers, Inc.
	Cemented surface with 150 sx of Class B cement with 2% CaCl2.
	Good circulation throughout job. Circulated cement to
	surface. Plug down at 11:00 PM on 10/28/88. Wait on cement.

- 10/30/88 Drilling ahead at 1795'.
- 10/31/88 Drilling ahead at 2457'.
- 11/01/88 Drilling ahead at 3327'.
- 11/02/88 Drilling ahead at 3957'.
- 11/03/88 TD well at 4165' at 3:15 PM on 11/2/88. Circulate 1 hour. Short trip. Trip out of hole for logs. Rigged up Welex. Ran IEL-CNL-FDC logs from loggers TD of 4157 ft. RKB. Trip in hole with drillpipe. Lay down drillpipe.
- 11/04/88 Finish laying down drillpipe and collars. Ran 4 1/2" casing as follows:

<u>Description</u>	Length	<u>Depth</u>
KB to landing point 120 jts. 4 1/2" 10.5#/ft J-55 new casing	12.00	0- 12
(Domestic-Maverick)	4088.68	12-4101
1 DFFC	1.60	4101-4102
1 jt. 4 1/2" 10.5#/ft casing	42.60	4102-4145
1 cement filled guide shoe	. 85	4145-4146
-	4145.73	

Centralizers at 4126, 3848, 3805, 3762, 3720 and 3678. Rigged up Halliburton. Cemented longstring with 200 sx (412 ft³) of Class B cement with 2% Econolite and 1/4# flocele/sx, tailed by 175 sx (221 ft³) of 50/50 pozmix with 2% gel, 10% salt and 1/4# flocele/sx. Good circulation throughout job. Bumped plug. Float held OK. Plug down at 12:30 PM on 11/3/88. Released rig. Wait on completion.