Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

P.O. Box 1980, Hobbit NM 88240 P.O. Box 2088	WELL API NO.
DISTRICT II Santa Fe, New Mexico 87504 P.O. Drawer DD, Arlesia, NM 88210	-2088 30-039-24326 5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No. E-178-1
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OR. GAS WELL WELL X OTHER	Northeast Blanco Unit
2 Name of Operator Blackwood & Nichols Co., Ltd.	8. Well No. NEBU #427
3. Address of Operator P. O. Box 1237, Durango, Colorado 813	9. Pool name or Wildcat Basin Fruitland Coal
4. Well Location Unit Letter N : 1140' Feet From The South	
Section 16 Township Runs	NMPM Rio Arriba County
10. Elevation (Show whether DF, RK)	, RT, GR, etc.)
11. Check Appropriate Box to Indicate Nature	of Notice, Report, or Other Data
NOTICE OF INTENTIONS OF	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUGUE ABANDON REM	EDIAL WORK ALTERING CASING
TEMPORARILY ABANDONAUGII3 1990 CHANGE PLANS COM	MENCE DRILLING OPNS. PLUG AND ABANDONMENT
LOCE OUT THE LAND TO A STATE OF THE PARTY OF	NG TEST AND CEMENT JOB
OTHER: DIST. 3 OTH	R:Convert to Pressure Observation Well X
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
12. Describe Proposed or Completed Operations (Clearly state at pertunent actaus, and give p work) SEE RULE 1103.	ertinent dates, including estimated date of starting any proposed
The NEBU #427 has been designated as The well is currently shut in waitin a string of 3/4" rods and an insert striped down to a master valve and twill be periodically run across to monitor formation pressure as ac produced. The designated proration unit for the striped designated designat	a pressure observation well. g on a workover unit to remove pump. The wellhead will be sest adaptor. A pressure bomb he Fruitland perforations to ljacent Fruitland wells are
The NEBU #427 has been designated as The well is currently shut in waitin a string of 3/4" rods and an insert striped down to a master valve and twill be periodically run across to monitor formation pressure as according to the Mesignated proration unit for the by the NEBU #427R (redrill).	a pressure observation well. g on a workover unit to remove pump. The wellhead will be sest adaptor. A pressure bomb he Fruitland perforations to ljacent Fruitland wells are
The NEBU #427 has been designated as The well is currently shut in waitin a string of 3/4" rods and an insert striped down to a master valve and twill be periodically run across to monitor formation pressure as ac produced. The designated proration unit for the by the NEBU #427R (redrill).	g a pressure observation well. g on a workover unit to remove pump. The wellhead will be test adaptor. A pressure bomb he Fruitland perforations to lijacent Fruitland wells are he NEBU #427 has been replaced
The NEBU #427 has been designated as The well is currently shut in waitin a string of 3/4" rods and an insert striped down to a master valve and twill be periodically run across to monitor formation pressure as accomproduced. The designated proration unit for the by the NEBU #427R (redrill).	a pressure observation well. g on a workover unit to remove pump. The wellhead will be sest adaptor. A pressure bomb he Fruitland perforations to ljacent Fruitland wells are
The NEBU #427 has been designated as The well is currently shut in waiting a string of 3/4" rods and an insert striped down to a master valve and the will be periodically run across the monitor formation pressure as accomplete to the best of my knowledge and belief. The designated proration unit for the by the NEBU #427R (redrill). Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TYPE OR FRINT NAME R. W. Williams	a pressure observation well. g on a workover unit to remove pump. The wellhead will be test adaptor. A pressure bomb he Fruitland perforations to ljacent Fruitland wells are le NEBU #427 has been replaced dministrative Manager DATE 8/13/40

OPHDITIONS OF APPROVAL, IF ANY: