UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	ices and Reports on Wells. 2:5	10	
Type of Well GAS	CO Administration	5.	Lease Number NM-012710 If Indian, All. or Tribe Name
GAD	61033	7.	Unit Agreement Name
. Name of Operator	SEP 2000		
BURLINGTON RESOURCES OIL	& GAS COMPANY O	8.	San Juan 30-6 Unit Well Name & Number
Address & Phone No. of Opera PO Box 4289, Farmington, NM	tor (87499 (505) \$26-9700	9.	San Juan 30-6 U #406 API Well No. 30-039-24484
. Location of Well, Footage, S 2560'FNL, 2610'FWL, Sec.15,	ec., T, R, M T-30-N, R-7-W, NMPM	10.	Field and Pool Basin Fruitland Coal
Z560 FNE, 2010 TWE, 550:50,		11.	County and State Rio Arriba Co, NM
, now mo Th	NDICATE NATURE OF NOTICE, REPOR	T, OTHER	DATA
 CHECK APPROPRIATE BOX TO IN Type of Submission 	Type of Action	,	
Notice of Intent	Abandonment Chan		
	Recompletion New	Construc	tion
X Subsequent Report	Plugging Back Non-	Routine	Fracturing
	Casing Repair Wate	r Shut o	ii - Trication
Final Abandonment	Altering Casing Conv	rersion t	o injection
	X Other - Pump installation)11	
7-21-00 MIRU. ND WH. NU 7-24-00 TIH, tag up @ 30 Establish circ @ 3076'. ND BO		3/8" 4./# rods. Lo	: 0-55 FOE CDG, Tandeo
7-21-00 MIRU. ND WH. NU 7-24-00 TIH, tag up @ 30 Establish circ @ 3076'. ND BO	BO. SD for weekend. 077'. TOOH w/99 jts 2 7/8" tbg. c. TOOH w/bit. TIH w/99 jts 2 3 OP. NU WH. TIH w/pump & 118 %"	3/8" 4./# rods. Lo	: J-55 FOE CDG, Tandeo
7-21-00 MIRU. ND WH. NU 7-24-00 TIH, tag up @ 30 Establish circ @ 3076'. ND BO	BO. SD for weekend. 077'. TOOH w/99 jts 2 7/8" tbg. c. TOOH w/bit. TIH w/99 jts 2 3 OP. NU WH. TIH w/pump & 118 %"	3/8" 4./# rods. Lo	: 0-55 FOE CDG, Tanded
7-21-00 MIRU. ND WH. NU 7-24-00 TIH, tag up @ 30 Establish circ @ 3076'. ND BO tbg & pump to	BO. SD for weekend. 077'. TOOH w/99 jts 2 7/8" tbg. c. TOOH w/bit. TIH w/99 jts 2 3 DP. NU WH. TIH w/pump & 118 %" 500 psi, OK. RD. Rig released.	78" 4.7# rods. Lo	: 0-22 FOF CDG, randed
7-21-00 MIRU. ND WH. NU 7-24-00 TIH, tag up @ 30 Establish circ @ 3076'. ND BO tbg & pump to	BO. SD for weekend. 077'. TOOH w/99 jts 2 7/8" tbg. c. TOOH w/bit. TIH w/99 jts 2 3 DP. NU WH. TIH w/pump & 118 %" 500 psi, OK. RD. Rig released.	78" 4.7# rods. Lo	oad hole w/wtr. PT
7-21-00 MIRU. ND WH. NU 7-24-00 TIH, tag up @ 30 Establish circ @ 3076'. ND BO tbg & pump to 14. I hereby dertify that the Signed Albert Acc	BO. SD for weekend. 077'. TOOH w/99 jts 2 7/8" tbg. c. TOOH w/bit. TIH w/99 jts 2 3 DP. NU WH. TIH w/pump & 118 %" 500 psi, OK. RD. Rig released.	78" 4.7# rods. Lo	eate 8/8/00
7-21-00 MIRU. ND WH. NU 7-24-00 TIH, tag up @ 30 Establish circ @ 3076'. ND BO tbg & pump to	BO. SD for weekend. 077'. TOOH w/99 jts 2 7/8" tbg. c. TOOH w/bit. TIH w/99 jts 2 3 DP. NU WH. TIH w/pump & 118 %" 500 psi, OK. RD. Rig released.	78" 4.7# rods. Lo	ed hole w/wtr. PT