UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Report	s on Wells		
1. Type of Well GAS	er i	6.	Lease Number SF-080711-A If Indian, All. or Tribe Name Unit Agreement Name
2. Name of Operator RESOURCES OIL & GAS COMPANY 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 3 4. Location of Well, Footage, Sec., T, R, M 595'FNL, 2135'FWL, Sec.31, T-30-N, R-6-W, N		9. 10.	Well Name & Number San Juan 30-6 Unit San Juan 30-6 Unit #58 API Well No. 30-039-25274 Field and Pool Blanco Mesaverde County and State Rio Arriba Co, NM
X Notice of Intent Abandonme Recomplet Subsequent Report Plugging Casing Re Final Abandonment Altering	ype of Action ent Change of tion New Const Back Non-Routi	f Plan truct: ine F: ut of:	ns ion racturing E
13. Describe Proposed or Completed Operation It is intended to run a spinner survey procedure and wellbore diagram.		accor	RECEIVED BLM the 99 JUL -2 AM 9: 04 to 070 FARMINGTON, NM
Signed May Madrice Title Required (This space for Federal or State Office use). APPROVED BY S Duane W. Spencer Title CONDITION OF APPROVAL, if any:	latory Administrator	tro	. 6/30/99 !!!L 2 0 100°

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

San Juan 30-6 Unit #58B

Unit C, Section 31, T30N, R06W Rio Arriba County, New Mexico Elevation 6836' GL, 6849' KB

LAT: 36° 46.4035' Long: 107° 30.3186'

Summary:

The San Juan 30-6 Unit #58B was spudded in August of 1993 and was originally completed in the Point Lookout, Menefee, Cliff House and Lewis in three stages. A spinner survey will be run on this well to help quantify the contribution of the Lewis in the 30-6 Unit. This data, along with data from other spinner surveys and the Shale Data Wells, will also be used in the completion design optimization of the Lewis.

Procedure:

1. Comply with all NMOCD, BLM, and BR regulations. Conduct daily safety meetings for all personnel on location.

DO NOT KILL WELL. ANY FLUIDS USED IN WELLBORE WILL INVALIDATE DATA. IF FLUIDS ARE REQUIRED, CONTACT MICHELE QUISEL TO DISCUSS ALTERNATIVES.

- 2. Inspect location and wellhead and install rig anchors prior to rig move if needed.
- 3. RU slickline unit. RIH w/ slickline and set tubing choke in FN @ 6182 ' (1.81" I.D. bore). RD slickline unit.
- 4. MIRU. Check all safety equipment to insure proper location and working order. ND wellhead and NU BOP, spool, stripping head and blooie line to pit. Continue to flow well through casing valve. Flow well through casing valve and blow well through blooie line to pit.
- 5. Strip199 jts. 2-3/8" 4.7# J-55 tubing through stripping head and stand back. SI rams on BOP. ND stripping head. Place well back on production down the line.

THE WELL WILL REMAIN ON PRODUCTION DURING THE ENTIRE SPINNER SURVEY.

- 6. RU Schlumberger and full lubricator. Open rams on BOP and RIH w/ spinner flowmeter tool/GR/CCL/Gradio. Correlate depth to GR/CCL logs provided by the engineer on location.
- 7. Take spinner survey readings at the following stations:

•	Station #1	4550'	Top of Navajo City Chacra
•	Station #2	4750'	Top of Otero Chacra
•	Station #3	4900'	Top of Middle Bench
•	Station #4	5300'	Top of Upper Cliff House
•	Station #5	5580'	Top of Massive Cliff House

8. Tag bottom w/ spinner tool. POOH w/ spinner flowmeter tool/GR/CCL/Gradio and SI rams on BOP. RD and release Schlumberger.

San Juan 30-6 Unit #58B

Unit C, Section 31, T30N, R06W Rio Arriba County, New Mexico Elevation 6836' GL, 6849' KB

LAT: 36° 46.4035' Long: 107° 30.3186'

9A. If fill, TIH w/ 3-7/8" bit and CO to PBTD. TOOH.

9. NU stripping head. Open rams on BOP. Strip 199 jts. 2-3/8" 4.7# J-55 tubing w/ expendable check and seating nipple one joint off bottom and land tubing @ 6214'. ND stripping head, BOP, spool, and blooie line. NU wellhead. Pump off expendable check. Place well on production. RD and release rig.

Recommend:

Production Engineer 6-22-99

Approve: Bruce W. Bongs 6-28-99
Drilling Superintendent

Approve: The and 6/22/99

Геат Leader

Vendors:

Wireline: Schlumberger 328-5006

 Michele Quisel
 Office: 324-6162
 Pager: 326-8196
 Home: 564-9097

 Steve Campbell
 Office: 326-9546
 Pager: 564-1902
 Home: 325-8218

 Hans Dube
 Office: 326-9555
 Home: 564-9401

 Glen Christiansen
 Office: 326-9733
 Home: 327-5089

San Juan 30-6 Unit #566

595' FNL, 2135' FWL Unit C Sec. 31, T-30 R-06W Rio Arriba County, New Mexico

KB 6849

GL 6836

LAT: 36 46.4035' LONG: 107 30.3186'

