UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

			5.	Lease Number
			J.	NM-4453
1. Type o : GAS			6.	
			7.	Unit Agreement Nam
2. Name o	f Operator			J
RES	SOURCES OIL	& GAS COMPANY		
3 Addros	s & Phone No. of Onese		8.	Well Name & Number
3Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700			9.	Carson SRC #100 API Well No. 30-039-26361
	on of Well, Footage, S		10.	Field and Pool
1055'F	SL, 1415'FWL, Sec.1, T	-30-N, R-5-W, NMPM	11.	Basin Fruitland Co County and State
				Rio Arriba Co, NM
12 CHECK	ADDRODRIATE BOY TO THE	DICATE NATURE OF NOTICE, R	POOD OFFI	73 m3
Type of	f Submission	Type of Action		DATA
	Notice of Intent	Abandonment	Thance of Pla	ans
v	Subsequent Penert	Recompletion 1	New Construct	ion
-^-	Subsequent Report	Casing Repair	Non-Routine E Water Shut of	racturing
	Final Abandonment	Casing Repair Nature Casing Casi	Conversion to	Injection
	cribe Proposed or Comp 2-00 MIRU. TIH w/130	_X_ Other - Install pump leted Operations rods & pump. Load hole w/w		· · · · · · · · · · · · · · · · · · ·
	cribe Proposed or Comp 2-00 MIRU. TIH w/130	_X_ Other - Install pump leted Operations		· · · · · · · · · · · · · · · · · · ·
	cribe Proposed or Comp 2-00 MIRU. TIH w/130	_X_ Other - Install pump leted Operations rods & pump. Load hole w/w		· · · · · · · · · · · · · · · · · · ·
	cribe Proposed or Comp 2-00 MIRU. TIH w/130	_X_ Other - Install pump leted Operations rods & pump. Load hole w/w		· · · · · · · · · · · · · · · · · · ·
	cribe Proposed or Comp 2-00 MIRU. TIH w/130	_X_ Other - Install pump leted Operations rods & pump. Load hole w/w		pump to 500
	cribe Proposed or Comp 2-00 MIRU. TIH w/130	_X_ Other - Install pump leted Operations rods & pump. Load hole w/w		pump to 500
	cribe Proposed or Comp 2-00 MIRU. TIH w/130	_X_ Other - Install pump leted Operations rods & pump. Load hole w/w		pump to 500
	cribe Proposed or Comp 2-00 MIRU. TIH w/130	_X_ Other - Install pump leted Operations rods & pump. Load hole w/w		pump to 500
	cribe Proposed or Comp 2-00 MIRU. TIH w/130	_X_ Other - Install pump leted Operations rods & pump. Load hole w/w		pump to 500
10-2	cribe Proposed or Comp 2-00 MIRU. TIH w/130 psi, OK. Circ	_X_ Other - Install pump leted Operations rods & pump. Load hole w/whhole clean. TOOH. RD.	tr. PT tbg &	pump to 500
10-2	cribe Proposed or Comp 2-00 MIRU. TIH w/130 psi, OK. Circ	_X_ Other - Install pump leted Operations rods & pump. Load hole w/w	tr. PT tbg &	pump to 500
10-2	cribe Proposed or Comp 2-00 MIRU. TIH w/130 psi, OK. Circ	_X_ Other - Install pump leted Operations rods & pump. Load hole w/whhole clean. TOOH. RD.	tr. PT tbg &	pump to 500
10-2	cribe Proposed or Comp 2-00 MIRU. TIH w/130 psi, OK. Circ	_X_ Other - Install pump leted Operations rods & pump. Load hole w/whole clean. TOOH. RD. foregoing is true and corn Title Regulatory Supers	tr. PT tbg &	pump to 500

Sm