

30-039-26479

Key Energy Services, Inc.

Four Corners Division 5651 US Highway 64 P.O. Box 900 Farmington, NM 87499

Phone: 505-327-4935 Fax: 505-327-4962

August 29, 2001

Rig No. 47

Phillips Petroleum Company 5525 Hwy 64 NBU 3004 Farmington, NM 87401

Attn: Patsy Clugston



This letter is to certify that Key Energy Services, Inc., did run deviation surveys at the listed depths on the San Juan 31-6 51M well in S05-T30N-R06W, in Rio Arriba county, New Mexico.

Depth	Deviation	Depth	Deviation
154'	0°	3021'	1/4°
306'	1/4°	3483'	1/2°
682'	½°	4145'	1°
1208'	1°	4641'	1/4°
1700'	1°	5170'	1⁄4°
2113'	½ °	5703'	1⁄4°
2606'	1½°	5980'	1°

To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith

Drilling contract manager

STAUDLICS

My commission expires:

C:\My Documents\Phillips\San Juan 31-6 51M.xls