

## **Amoco Production Company**

Petroleum Center Building 501 Airport Drive Farmington, New Mexico 87401 505 - 325-8841

R. W. Schroeder District Superintendent

June 10, 1980

Mr. Frank Chavez New Mexico Oil Conservation Commission 1000 Rio Brazos Road Aztec, New Mexico 87410

File: RAD-91-416

Mr. Chavez:

Amoco's Working, Royalty Interest in the Gallegos Canyon Unit Well No. 2

Pursuant to our conversation of this date, Amoco hereby notifies your office that we no longer have a working interest or royalty interest in the Gallegos Canyon Unit Well No. 2. Our interest in the subject well was sold to Clinton Oil Company in December 1959.

Yours very truly,

000/±1

JUN 12 1960 OIL OSST. 3



BRUCE KING

GOVERNOR

LARRY KEHOE SECRETARY ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

April 6, 1981

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

Mr. Albert Greer Jr.
Benson-Montin-Greer Drilling Corporation
501 Airport Drive
Farmington, N.M. 87401

Re: Gallegos Canyon Unit #2 K-35-29N-12W

Dear Al:

I have talked to you several times since our first telephone conservation in September concerning the referenced well and as yet have not received a satisfactory response. You are therefore directed to file a notice of intention to plug and abandon the well within thirty (30) days. A plugging program for the well will include but not be limited to the following:

cement plug from 1250' - 1448' (TD)

'' '' 400' - 500'

'' '' 225' - 325'

surface plug and marker.

After approval of the application you will have ninty (90) days to perform the work.

If you have any quest on please contact this office.

Yours truly,

Frank T. Chavez District Supervisor

FTC/1s

Xc: Santa Fe, Ernie Padilla Reading file





## ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

March 4, 1982

Mr. Perry Pearce Oil Conservation Division P. O. Box 2088 Santa Fe, NM 87501

Re: Forced plugging cases

Dear Perry,

Please docket the following cases:

- A case to allow A. H. Bernstein and other interested parties to appear and show cause why the Allan #1 located in F-23-29N-13W should not be reentered and plugged in accordance with a division approved plugging program.
- 2. A case to allow F. B. Umbarger, Trustee, and other interested parties to appear and show cause why the Davis Pooled Unit #1 located in I-27-29N-11W should not be reentered and plugged in accordance with a division approved plugging program.
- 3. A case to allow Francis L. Harvey and other interested parties to appear and show cause why the Pinkstaff Estate #1 located in A-29-29N-10W should not be reentered and plugged in accordance with a division approved plugging program.
- 4. A case to allow B.M.N.S. Company, American Employers Insurance, and other interested parties to appear and show cause why the Waggoner #1 located in K-29-30N-12W, the Brown #2 located in M-29-30N-12W, and the Wyper #2 located in O-29-30N-12W should not be plugged in accordance with a division approved plugging program.

Mr. Perry Pearce March 4, 1982 Page two

- 5. A case to allow Pauly-Anderson-Pritchard and other interested parties to appear and show cause why the Maloy #1 should not be plugged in accordance with a division approved plugging program.
- 6. A case to allow E. J. Miley and other interested parties to appear and show cause why the Hare (Ransom) #1 should not be plugged in accordance with a division approved plugging program.
- 7. A case calling Benson-Montin-Greer Drilling Corporation, Hartford Accident and Indemnity Company, and other interested parties to appear and show cause why the Dustin #1 located in K-6-29N-12W, the Segal #1 located in K-10-31N-13W, the Price #1 located in N-15-31N-13W, and the Gallegos Canyon Unit #2 located in K-35-29N-12W should not be plugged in accordance with a division approved plugging program.
- 8. A case to allow Calvin Petroleum Corporation to appear and show cause why the Kaempf SWD #1 located in N-19-30N-11W should not be plugged in accordance with a division approved plugging program, and why the operator should not be found in violation of Rule 101 and fined accordingly.

Yours truly,

Frank T. Chavez District Supervisor

FTC:gc

BENSCN & MONTIN
Gallegos Canyon Unit #2
K-35-29N-12W
Wellbore Diagram

