Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lesse Designation and Serial No. SF-078931-D

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.


Use "APPLICATION FOR PERMIT—" for such proposals

OU ALLEGATION TO	M. L. Cittani I	<u>_</u>
SUBMI	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
i. Type of Well		8. Well Name and No.
X Well Gas Other		
2. Name of Operator		Callow Fed. #2
Great Western Drilling Compan	Y	9. API Well No.
3. Address and Telephone No.		
2550 La Plata Hwy, Farmington	N. M. 87401 327-0494	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey I		Totah Gallup
2275' FSL and 1810' FEL		11. County or Parish, State
22/5 FSL and 1010 FEB		·
		33 T-29N R-13W
CUECK APPROPRIATE BOY	(s) TO INDICATE NATURE OF NOTICE, I	
12. CHECK APPHOPHIATE BOX	S) TO INDICATE NATURE OF NOTICE,	LEFORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Nor-Routine Fracturing
	X Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of studtiple completion on Web Completion or Recompletion Report and Log form.
13 Describe Proposed or Completed Operations (Clearly state of	Il pervinent details, and give perunent dates, including estimated date	of starting any proposed work. If well is directionally drill

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drift give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Intend to pull rods and tubing out of well run retreivable bridge plug and set at 5300' +or- spot sand on top of bridge plug run packer and test tubing and Bridge plug to 2000# then locate top and bottom holes in casing and squeeze with 100 sx 65-35 poz followed by 25 sx class b neat drill out and test squeeze, resqueeze if neccessary if not rerun rods and tubing and return well to production.

PECHLYED
92 MAR - Is AM 10: LA I



14. I hereby certify that the foregoing is true and correct Signed John B. Tieling S.	APPROVED The Division prod. and Drlg Supervisor Date	
(This space/for Federal or State office use)		<u>in 4</u> ₹ 0 5 1992
Approved by Conditions of approval, if any:	NMOOD	AREA MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.