

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

1 01111 1	pp. v. out
Land Offic	Santa Fe
Lease No.	<b>SF-078931-B</b>
II_1A	

Budget Bureau No. 42-R358.4.

INDRY NOTICES	AND	REPORTS	ON	WFI.	I.S
---------------	-----	---------	----	------	-----

		SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	A	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		II
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT.
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		Febr	uary 20		, 19 <b>62</b>
Well No. 3 is located in the second s		from $S$ lin	ne and 1850	ft. from $\left\{\begin{matrix} \mathbf{F} \\ \mathbf{W} \end{matrix}\right\}$ line of s	ec. <b>3</b> 1
NE/4 Section 31	<b>29</b> N	13W	MAPH	,	
(1/2 Sec. and Sec. No.) Cha Cha Gallup	(Twp.) Sirr	(Range)	(Mer	Rev Mexico	M Inc.
The elevation of the derrick	,	ounty or Subdivision callevel is 587		(State or or or or)	
	DE	TAILS OF	WORK	•	6 1952
(State names of and expected depths to	o objective sands; sh ing points, an	d all other import	and lengths of pro ant proposed work	posed casings; indical anuadir Dis	ng Jobs, coment

- 1. Not complete Dakota formation at this time as originally planned.
- 2. Set bridge plug and cast 6 5690 and complete in Gallup only.

Note: This Gallup production is estimated to be short lived. When Gallup is depleted we will again look at Dakota for possible completion in that formation.

I understa	and that this plan of work must receive approval in	writing by the Geological Survey before operations may be commenced.
Company	Tenneco Corp., acting by and	thru its managing agent Tenneco Oil Company
Address	P. 0. Box 1714	By Blumb. B. Plumb
Durango, Colorado		By / 100 MCCALL. B. Plumb
		Title Strict Production Superintendent