

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(See instructions on re-  
verse side)Form approved  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-2168

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

NW Cha Cha

8. FARM OR LEASE NAME

NW Cha Cha Unit

9. WELL NO.

41-34

10. FIELD AND POOL, OR WILDCAT

Cha Cha Gallup

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 34-29N-14W NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

N. M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Humble Oil &amp; Refining Company

3. ADDRESS OF OPERATOR

P. O. Box 120, Denver, Colorado 80201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

NE NE (560' FNL, 560' FEL) Sec. 34

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5792'KB

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

10-12-72 Spot 15 sack cement plug 5322-5222

Spot 15 sack cement plug 4500-4400

10-14-72 Shot casing @ 1500'. 40 sxs cement plug inside and outside casing from  
1400' to 1500'.

Shot casing @1250'. Spot 40 sxs cement plug from 1250 to 1150.

Shot casing off @ 1080. Pulled casing.

10-16-72 Spot 40 sack cement plug from 218' to 118'.

Spot 15 sace cement plug from 30' to 0'.

Installed regulation dry hole marker and cleaned location for inspection.

Intervals between plugs filled with gelled mud.

CC: 2-New Mexico Oil Conservation Commission

1-Minerals Supervisor-Navajo Tribe

1-Midland

18. I hereby certify that the foregoing is true and correct

SIGNED

J. Roy Dorrrough

TITLE

District Superintendent

DATE

12/1/72

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side