Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-entergance abandoned well. Use Form 3160-3 (APD) for such proposals.

14-20-603-2172
67 If Indian, Allottee or Tribe Name

5. Lease Serial No.

		1	MANADO MATTOM	
Type of Well			If Unit or CA/Agreement, Name and/or No.	
			NW CHA CHA UNIT	
	🖾 Oil Well 🚨 Gas Well 🚨 Other	8.	Well Name and No. NW CHA CHA UNIT 59	
2.	Name of Operator			
	MOUNTAIN STATES PETROLEUM CORP.	9.	API Well No.	
3a.	Address 3b. Phone No. (include area code)		30-045-07772	
	P O BOX 3531, MIDLAND, TX 79702 915/685.0878	10	. Field and Pool, or Exploratory Area	
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description)		HA CHA GALLUP	
	M	11	. County or Parish, State	
	660' FSL & 660' FWL Sec. 26, T19N R14W NMPM		SAN JUAN, NEW MEXICO	
			· · · · · · · · · · · · · · · · · · ·	

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Well Integrity Other					

- 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)
 - 1) RIH, drill out CIBP set at 3375'.
 - 2) Tag CIBP set at 5250'. Set 28 sx Class G Neat cement to 4962', 50' above Gallup top at 5012'.
 - 3) Set CIBP at 2787', 50' above top perf in Mesaverde. Set 15 sx Class G Neat cement plug inside casing.
 - 4) Set 15 sx Class G Neat cement plug 1340-1240' inside casing. Picture Cliff top at 1290'.
 - 5) Set 36 sx Class G Neat cement plug inside and outside casing from 800-900', 50' above Fruitland top at 850'.
 - 6) Set 120 sx plug from 271' to surface inside and outside casing from 50' below casing shoe at 221'.

DECEIVE

 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Brian M. Sirgo 	Title	Agent	OIL CON. DIV. DIST. 3
Signature Prayti- 15	Date	September 25,	, 1997
THIS SPACE FOR I	FEDERAL OR S	STATE OFFICE USE	
Approved by /S/ Duane W. Spencer	1.	Title	Date OCT - 1 1997
Conditions of approval, if any, are attached. Approval of this notice does certify that the applicant holds legal or equitable title to those rights in the which would entitle the applicant to conduct operations thereon.	Office		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.