Form 3160-5 (June 1990) D. BU	UNITED STATE EPARTMENT OF THE REAU OF LAND MAN	INTERIOR		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.			
SUNDRY Do not use this form for prop Use "APPLIC	14-20-603-2172 6. If Indian, Allottee or Tribe Name Navajo Nation 7. If Unit or CA, Agreement Designation NW Cha Cha Unit						
SUBMIT IN TRIPLICATE							
1. Type of Well Gas Well Well Other		8. Well Name and No. NW Cha Cha Unit 58 9. API Well No.					
2. Name of Operator MOUNTAIN STATES PI							
Address and Telephone No. P O BOX 3531, MID: Location of Well (Footage, Sec., T., R.,		30-045-07779 10. Field and Pool, or Exploratory Area Cha Cha Gallup					
760' FSL & 1980' FE		N, Rl4W, NMPM		11. County or Parish, State San Juan, NM			
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION		TYPE	OF ACTION				
Notice of Intent		Abandonment Recompletion		Change of Plans New Construction			
Subsequent Report		Plugging Back		Non-Routine Fracturing			
Final Abandonment Notice	:	Casing Repair Altering Casing		Water Shut-Off Conversion to Injection			
13 Describ Brown of Co. 1 10		L.J Other		Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
give subsurface locations and measure	s (Clearly state all pertinent details, and true vertical depths for all n	and give pertinent dates, including estimaters and zones pertinent to this work	ited date of starting : .)*	any proposed work. If well is directionally drilled,			
We request approval to plug and abandon this well in accordance with the attached procedure							
Plugging will b	e completed	by June 1, 199	₁ ¬ ,	97 APR -			
		PEGEL APR - 0 120		RECEIVED 97 APR -1 FILLS 19 070 TV3.5550004 553			
		OIL COM. Dist. a					

14. I hereby certify that the foregoing is true and object

Signed

Title Agent

Date 4//97

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Andrew Commencer

NW CHA CHA UNIT SAN JUAN COUNTY, NEW MEXICO

PROCEDURE TO P&A WELL NO. 58

- 1. Move in & rig up pulling unit
- 2. Set bridge plug 50' above top perf
- 3. Spot cement to 50' above Gallup
- 4. Shoot casing and recover casing
- 5. Set plug in and out of top of casing, 100' plug w/25 sx cement
- 6. Set 100' plug w/30 sx cement across Cliffhouse formation
- 7. Set 100' plug w/30 sx cement across Fruitland/Picture Cliffs formation
- 8. Set 25 sx cement plug at surface
- 9. Install dry hole marker

		A.V. Y