

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Aramis, NM 88210

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Grande Rd., Aztec, NM 87410

WELL API NO.
30-045-07800

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

SALMON

2. Name of Operator
CONOCO INC.

8. Well No.
1

3. Address of Operator
10 Desta Drive STE 100W, Midland, TX 79705

9. Foot name or Wildcat
BASIN DAKOTA (GAS)

4. Well Location
Unit Letter P : 1190 Feet From The SOUTH Line and 990 Feet From The EAST Line
Section 30 Township 29 N Range 11 W NMPM SAN JUAN County

10. Direction (Show weather DP, RKB, RT, CM, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-17-93 MIRU. POOH W/ 188 JTS 1 1/4" TBG. GIH W/ 4 1/2" CMT RETAINER SET @ 5808', MIX 35 SX CLASS 'B' CMT SQUEEZE 30 SX UNDER RETAINER AND SPOT 5 SX ON TOP. LEFT RETAINER SETTING TOOL & 20 JTS 2" TBG IN WELL FROM 5113' TO 4505'. PLUG 2 FROM 4505 TO 4346' 12 SX CLASS 'B' CMT ON TOP OF TBG STUB. PERF 4 HOLES @ 3050'. GIH W/ 4 1/2" CMT RETAINER SET @ 2990'. MIX 51 SX CLASS 'B' CMT, SQUEEZE 46 SX UNDER CR & SPOT 5 SX ON TOP. CIRCULATE HOLE CLEAN. PLUG 4 12 SX CLASS 'B' CMT FROM 1502' TO 1344'. PLUG 5 12 SX CLASS 'B' CMT FROM 993' TO 835'. POOH. PERF 2 HOLES @ 395'. ESTABLISH CIRC OUT BRADENHEAD. PLUG 6. FROM 395' TO SUFRACE W/ 174 SX CLASS 'B' CMT W/ 2% CACL. CIRC 1 bbl GOOD CMT OUT BRADENHEAD, WOC FOR 2 1/2 hrs. CUT OFF WELLHEAD. INSTALL P&A MARKER W/ 20 SX CMT. PLUG 7. FROM SURFACE INTO 9 5/8" & 4 1/2" CSG STUBS W/ 97 SX CLASS 'B' CMT, PRESSURED UP T 11-24-93 RDMO. WELL IS P&A'ed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill R. Keathly TITLE SR REGULATORY SPEC. DATE 12-16-93
TYPE OR PRINT NAME BILL R. KEATHLY TELEPHONE NO. 915-686-5424

(This space for State Use)

APPROVED BY Henry G. Fount TITLE Geologist DATE 12/27/94
CONDITIONS OF APPROVAL, IF ANY: