Form	3160-5
(June	1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED			
Bugget Bureau No. 1004-0135			
Expires: March 11 1003			

SF.	0	79065	
-	_	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

SUNDRY NOTICES AND REPORTS ON WELLS, A 1 PT 12: 18 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

1. Type of Well		
Oil Gas Other		8. Well Name and No.
2. Name of Operator		5 Azrec Totah D
Paramount Petroleum ( 3. Address and Telephone No.	orp. To NMOCD	9. API Well No.
		300450 7833
A Location of Well (First Pos Rd)	Azrec, Nm 87910 334-6178 Description)	10. Field and Pool, or Exploratory Area
		Torah Gallup
1630/5 × 1570/W Sec. 29, 7.2	19N. R.13W.	11. County or Parish, State
		San Juan, NM
12. CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPOF	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
<b>1</b> 71	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	U Other	Dispose Water
13. Describe Proceeds Constitution		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give subsurface locations and measured and true vertice	l pertinent details, and give pertinent dates, including estimated date of starting all depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled,

See attached Report for Pak

011 GON. DIV. dist. 3

4. I hereby certify that the foregoing is true and correct		
Signed NMOCO CONTIACT	Title	Date 5/21/98
(This space for Federal or State office use)		
Approved by ASI Duane W. Spencer Conditions of approval, if any:	Tide	Date MAY 2   1998

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## TRIPLE P WELL SERVICE, INC.

## **AZTEC TOTAH #5**

RIG 6

START 3/11/98

END 3/17/98

- 1. Shoot backoff charge @ 5030'. Pull out 5040' tubing.
- 2. Trip in workstring. Circulate well clean 5040'. Trip out, trip in hole with 4-1/2" scraper to 5040'.
- 3. Trip in hole with 4-1/2" packer, test pipe @ 5030'. OK.
- 4. Trip in hole, spot 40sx, 47cf cement plug.
- 5. Tag plug with wireline @ 4589'. Shoot 4 squeeze holes @ 2840'.
- 6. Set cement retainer @ 2810'. Mix and pump 55sx, 65cf cement.
- 7. Displace and balance 45sx, 53cf cement @ 1260'.
- 8. Shoot 4 squeeze holes @ 253'. Circulate 100sx, 118cf cement to surface.