

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Union Texas Petroleum Corporation	8. Farm or Lease Name Armenta
3. Address of Operator P. O. Box 1290, Farmington, New Mexico 87499	9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> <u>2190</u> FEET FROM THE <u>North</u> LINE AND <u>820</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>29N</u> RANGE <u>10W</u> NMPM.	10. Field and Pool, or Wildcat Aztec PC SJ Undes. Farm Sand
15. Elevation (Show whether DF, RT, GR, etc.) 5517' DF	12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Squeeze Casing Leak</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

MIRUSU. Pull Farmington tubing and Pictured Cliffs tubing and packer. Set BP at 1720. Locate casing leak and squeeze with cement as required. Drill out, pressure test, and resqueeze if necessary. Drill BP and clean out to TD. Rerun Pictured Cliffs tubing and packer. Rerun Farmington tubing and resume production.

RECEIVED

NOV 01 1984

OIL CON. DIV.  
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED P. M. Pippin TITLE Sr. Petroleum Engineer DATE 10/30/84

Original Signed by FRANK T. CHAVEZ

SUPERVISOR DISTRICT # 3

NOV 01 1984

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY: