Submit 3 Copies to-Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brizos Rd., Aziec, NM 87410	· ·	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Lefkovitz Gas Com "B"
1. Type of Well: OIL GAS WELL WELL	X OTHER	
2 Name of Operator Amoco Production Company Attn: J. L. Hampton		8. Well No.
3. Address of Operator P.O. Box 800, Denver, Colorado 80201		9. Pool name or Wildcat Basin Dakota
4. Well Location Unit Letter A : 1	150 Feet From The North Line and 790	Feet From The East Lin
Section 25	Township 29 North Range 10 West	NMPM San Juan County
	10. Elevation (Show whether Dr., KAB, KI, GR, etc.)	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
	(//////	<u> </u>
	k Appropriate Box to Indicate Nature of Notice, R	-
NOTHERD	SUE	BSEQUENT REPORT OF:
NOTSEIOF	PLUG AND ABANDON REMEDIAL WORK	BSEQUENT REPORT OF: ALTERING CASING
PERFORM REMEDIAL MORK TEMPORARILY ABANDON MAR	PLUG AND ABANDON REMEDIAL WORK 1 1981 ANGE PLANS COMMENCE DRILLIN	BSEQUENT REPORT OF: ALTERING CASING G OPNS. PLUG AND ABANDONMENT
PERFORM REMEDIAL MORK TEMPORARILY ABANDON MAR PULL OR ALTER CASINO 1	PLUG AND ABANDON REMEDIAL WORK	BSEQUENT REPORT OF: ALTERING CASING G OPNS. PLUG AND ABANDONMENT

- 2. Set RBP @ 3524'. Set PKR @ 63'.
- 3. E.T.T. log from 6150' to 3550'. Ran CBL from 2200' to 50'.
 4. Set RBP @ 3224'. Set PKR @ 180'. Test to 700 psi. Held. Dumped 2 sx sand on RBP.
- Pump 15 sx Class B. cmt. Circ cmt to surface. (BPM and 250 psi)
- 6. Drill cmt to 45'.
- 7. Pressure test casing to 500 psi. Held.
- 8. Isolated leak at 3850' to 3952'.9. TIH with cmt stinger. Stung into cmt retainer @ 3850'.
- 10. Pump 30 sx Class B cmt and 50 sx Class B neat tail.
- 11. Sq stung out of retainer and reversed out 3.5 BBLS cmt. TOH cmt stinger.
- 12. Drill cmt and cmt retainer to 3952'. Pr tst csg to 500 psi. Held.

I hereby certify that the information above is true and complete	to the best of my knowledge and belief.	- 1 . 1 a .
SIGNATURE JAMES A	Sr. Staff Admin. S	UDV. DATE 3/5/91
TYPE OR PRINT NAME		TELEPHONE NO.

Original Signed by FRANK T. CHAVEZ

SUPERVISOR DISTRICT #3

MAR 1 1 1991

Lefkovitz Gas Com "B" #1

- 13. Release RBP @ 4050'. Pr tst csg to 6224' to 500 psi. Held.
- 14. TOH RBP. Land tbg @ 6424'. 15. Return well to production.

Please call Cindy Burton at 303-830-5119 if you have any questions.