

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
<p>1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		7. Unit Agreement Name
<p>2. Name of Operator <u>Roy L. Cook</u></p>		8. Farm or Lease Name <u>Davie</u>
<p>3. Address of Operator</p>		9. Well No. <u>1</u>
<p>4. Location of Well UNIT LETTER <u>I</u>, <u>2275</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>685</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>23</u> TOWNSHIP <u>29N</u> RANGE <u>11W</u> NMPM.</p>		10. Field and Pool, or Wildcat <u>Aztec Fruitland</u>
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p>		12. County

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Well indicates casing failure - Flowing water outside Surface Casing - will pull tubing, enter well, locate hole, set plug, squeeze cement head, test & return to production

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE [Signature] DATE 8-20-74

APPROVED BY [Signature] TITLE SUPERVISOR DIST. #3 DATE 8-20-74

CONDITIONS OF APPROVAL, IF ANY:

