

## State Scents Gas Leak Cause

11/10/63  
Officials from the New Mexico Energy and Minerals Department may have found the source of the gas leak which resulted in two homes being evacuated on Camino Rio Drive two weeks ago.

Frank Chavez, a district supervisor with the state agency, said that an old gas well was located in the backyard of Dale Nettleton's residence. Chavez said it is very possible that the old well is the source of the dangerous levels of gas found under houses owned by Harold Roberts and Winnie Brady.

The gas leak was found when a crew from the Gas Company of New Mexico was testing the lines last week. The state was called in when the gas company realized it may not have been its lines causing the problem.

Chavez said that crews are presently trying to plug the well. Shortly after that, hopefully by Friday, it should be known whether the gas leaks are coming from the old well, which was drilled in 1955-56.

discrepancy between revenues and salary

## State Scents Gas Leak Cause

Officials from the New Mexico Energy and Minerals Department may have found the source of the gas leak which resulted in two homes being evacuated on Camino Rio Drive two weeks ago.

Frank Chavez, a district supervisor with the state agency, said that an old gas well was located in the backyard of Dale Nettleton's residence. Chavez said it is very possible that the old well is the source of the dangerous levels of gas found under homes owned by Harold Roberts and Winnie Brady.

The gas leak was found when a crew from the Gas Company of New Mexico was testing the lines last week. The state was called in when the gas company realized it may not have been its lines causing the problem.

Chavez said that crews are presently trying to plug the well. Shortly after that, hopefully by Friday, it should be known whether the gas leaks are coming from the old well, which was drilled in 1955-56.