

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Bureau No. 42-R1421.  
5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-2199

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Northwest Cha Cha	
2. NAME OF OPERATOR Humble Oil & Refining Company		8. FARM OR LEASE NAME Northwest Cha Cha Unit	
3. ADDRESS OF OPERATOR P O Box 120, Denver, Colorado 80201		9. WELL NO. 21-21	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  NESW(660' FNL & 1890' FWL) of Section 21		10. FIELD AND POOL, OR WILDCAT Cha Cha Gallup	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 21-29N-14W NMPM	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5213' KB	12. COUNTY OR PARISH San Juan	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	



SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 1-5-72 - Placed 15 sack cement plug 4726-4626', 15 sack cement plug 3850-3750'.
- 1-6-72 - Shot and pulled 5½" casing from 2080'.
- 1-7-72 - Spot 40 sack cement plug 900-800', 40 sack cement plug 540-640', 40 sack cement plug 260-160'.
- 1-8-72 - Set regulation dry hole marker in top of surface casing with 12 sack cement plug from 30-0'.  
Intervals between plugs filled with mixed mud.
- 2-7-72 - Location cleaned ready for inspection.



- cc: 2 - NM O&G Commission  
1 - Minerals Supervisor - Navajo Tribe  
1 - Midland  
1 - Clinton

18. I hereby certify that the foregoing is true and correct

SIGNED \_\_\_\_\_ TITLE Dist. Superintendent DATE 2-9-72

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: