

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

RECEIVED
JAN 20 1998

50 JAN -9 PM 3:39

070 TOWN & LAND

5. Lease Number
SF-077056
6. If Indian, All. or
Tribe Name

2. Name of Operator **OIL CON. DIV.**
BURLINGTON DIST. 3
RESOURCES OIL & GAS COMPANY

7. Unit Agreement Name

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

8. Well Name & Number
Cozzens #19. API Well No.
30-045-08238

4. Location of Well, Footage, Sec., T, R, M
1320' FSL, 1570' FWL, Sec. 18, T-29-N, R-11-W, NMPM

10. Field and Pool
Basin Fruitland Coal/
~~Fulcher Kutz PC~~
11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment

Type of Action

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other -
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut off
☐ Conversion to Injection

13. Describe Proposed or Completed Operations

- 11-21-97 MIRU. ND WH. NU BOP. TOO H w/59 jts 1 1/4" tbg. TIH w/gauge ring to 1600'. TOO H. TIH w/CIBP, set @ 1600'. Load hole w/wtr. PT csg to 1000 psi, OK. Perf 4 sqz holes @ 1595'. Attempt to establish injection. Perf 4 sqz holes @ 1545'. Attempt to establish injection. SD for weekend.
- 11-24-97 TIH, tag CIBP @ 1600'. Establish circ. Plug #1: pump 5 sx Class "B" neat cmt inside csg @ 1500-1600'. TOO H. TIH, perf 4 sqz holes @ 777'. Attempt to establish injection w/30 bbl wtr. Plug #2: pump 340 sx Class "B" neat cmt out side csg @ 492-777'. Pump 15 sx Class "B" neat inside csg. TOO H. WOC. TIH, tag TOC @ 190'. Perf 4 sqz holes @ 110'. Attempt to establish injection w/40 bbl wtr. (Verbal approval to change plans from Steve Mason, BLM). Plug #3: pump 110 sx Class "B" neat cmt inside csg @ 60-110'. No cmt to surface. Sqz to 500 psi. WOC. SDON.
- 11-25-97 TIH, tag TOC @ 59'. TIH, perf 2 sqz holes @ 50'. Establish circ w/30 bbl wtr. Plug #4: pump 100 sx Class "B" neat cmt outside csg. WOC. ND BOP. Cut off WH TOC inside csg @ surface. Install dry hole marker w/20 sx Class "B" neat cmt Well plugged and abandoned 11-25-97. (M. Deaton, C. Gall, BLM on location for all plugging operations).

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 1/5/98

(This space for Federal or State Office use)

APPROVED BY /s/ Duane W. Spencer Title _____ Date JAN 15 1998