

NO. 1-8 COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-7844
7. Unit Agreement Name
8. Farm or Lease Name Foutz State
9. Well No. 1
10. Field and Pool, or Wildcat Cha Cha Gallup
12. County SJ

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Southwest Production Company	8. Farm or Lease Name Foutz State
3. Address of Operator P. O. Box 400, Aztec, N.M.	9. Well No. 1
4. Location of Well UNIT LETTER J 1912 FEET FROM THE S LINE AND 2310 FEET FROM THE E LINE, SECTION 16 TOWNSHIP 29 N RANGE 14 W NMPM.	10. Field and Pool, or Wildcat Cha Cha Gallup
15. Elevation (Show whether DF, RT, GR, etc.) KB 5194'	12. County SJ

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/11/67 - Starting date for pulling casing and setting cement plugs as follows:

#1 - 4640' - 4740'.

#2 - 50' @ cut-off stub.

#3 - 550' - 650'.

#4 - 30' plug in surface pipe with 4" pipe marker with Company,
name and well location on it.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>F. B. C. [Signature]</i></u>	TITLE <u>Production manager</u>	DATE <u>5/10/67</u>
APPROVED BY <u><i>[Signature]</i></u>	TITLE <u>SUPERVISOR DIST. #3</u>	DATE <u>MAY 12 1967</u>
CONDITIONS OF APPROVAL, IF ANY:		