

(SUBMIT IN TRIPLICATE)

Indian Agency

Navajo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee

Lease No. 1-89-IND-56

		X	

Sec. 12
SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	X	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

CONFIDENTIAL

May 11, 1962

Well No. 143 is located 1980 ft. from [N] line and 2125 ft. from [E] line of sec. 12

SE/4 Sec. 12 T29N R19W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Rattlesnake San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5293 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

While coming out of hole for bit change, pick-up sub parted and 9 drill collars, Bowen bumper jars, and 8 3/4" bit dropped to bottom. Fished 2 drill collars from hole, unable to get over remaining fish, top of fish @ 4764' RB, bottom of fish @ TD of 4950' RB. Spotted 50 sack cement plug on top of fish, WOC 13 hours and drilled out plug to 4670', bottom of intermediate string @ 4650'. We propose to set whip-stock @ 4670' and side-track fish. Well will be completed as stated on initial sundry notice.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 3312

Durango, Colorado

By [Signature]
Title Asst. District Supt.

1. The first of these is the fact that the Commission has not yet received any information from the Government of the United States regarding the activities of the Committee for the Liberation of the Americas (CLA) in the United States. The Commission is therefore unable to determine whether the CLA is a legitimate organization or a subversive one.

[illegible][illegible]

Journal of Management Studies, 19(6), 701-718.

...the ...