UNITED STATES D

ONTILD DIMILED								
DEPARTME	ENT	OF	THE	INTER	IOF			
BUREAU	OF	LAN	ID MZ	ANAGEM	ENT			

Sundry Notic	ses and kepor			
			5.	Lease Number
. Type of Well GAS			6.	SF-068990 If Indian, All. of Tribe Name
			7.	Unit Agreement Nam
. Name of Operator				-
BURLINGTON				
oil &	GAS COMPANY		8.	Well Name & Numbe
. Address & Phone No. of Operato				Hudson #1
PO Box 4289, Farmington, NM	87499 (505)	326-9700	9.	API Well No. 30-045-08579
. Location of Well, Footage, Sec			10.	Field and Pool
1750'FNL, 1090'FEL, Sec.8, T-2	29-N, R-12-W,	NMPM	11.	Basin Dakota County and State San Juan Co, NM
2. CHECK APPROPRIATE BOX TO INDI	CATE NATURE	OF NOTICE, RE	PORT, OTHER	DATA
Type of Submission	T	ype of Action	Ļ	
Notice of Intent	Abandonm Recomple	ent C tion N	Change of Pla New Construct	
X Subsequent Report	Plugging Casing R	Back N	Mon-Routine E Mater Shut of	racturing
Final Abandonment	Altering	Casing C	Conversion to	
	X Other -	Tubing repair	•	
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	TIH w/202 jts 2 3, WH. RD. Rig releas
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629	30P. TOOH w/2 90'. Circ & C	ns 3/8" tbg. SI O to PBTD @ 6	399'. TOOH.	WH. RD. Rig releas
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629 4.7# J-55 tbg,	BOP. TOOH w/2 90'. Circ & C set @ 6291'	ns 3/8" tbg. SI O to PBTD @ 6 . SN @ 6258'.	3399'. TOOH. ND BOP. NU	WH. RD. Rig releas
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629 4.7# J-55 tbg,	GOP. TOOH w/2 90'. Circ & C set @ 6291'	ns 3/8" tbg. SE O to PBTD @ 6 . SN @ 6258'.	S399'. TOOH. ND BOP. NU	WH. RD. Rig releas
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629 4.7# J-55 tbg,	GOP. TOOH w/2 90'. Circ & C set @ 6291'	ns 3/8" tbg. SI O to PBTD @ 6 . SN @ 6258'.	S399'. TOOH. ND BOP. NU	WH. RD. Rig releas
1-8-01 MIRU. ND WH. NU E 1-10-01 TIH, tag up @ 629 4.7# J-55 tbg,	Foregoing is Title	ns 3/8" tbg. SE O to PBTD @ 6 . SN @ 6258'.	S399'. TOOH. ND BOP. NU	WH. RD. Rig releas