

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**

Lease No. **065557-A**

Unit

RECEIVED

JAN 13 1961

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 13

1961

Cornell Dakota Gas Unit "A"

Well No. **1** is located **1180** ft. from **[N]** line and **790** ft. from **[E]** line of sec. **10**

NW/4 Section 10

(1/4 Sec. and Sec. No.)

R9N

(Twp.)

12W

(Range)

10PM

(Meridian)

Undesignated

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

ground level

The elevation of the ~~derick floor~~ above sea level is **5679** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Running and cementing production casing as follows:

Ran 20.3 joints 4 1/2" OD, 9.5#, J-55 casing, total footage 6484' set at 6494'. Stage collar set at 2006 and cemented in two stages. 1st stage, cemented with 200 sacks 50-50 Pozmix, 6% gel, followed by 50 sacks 50-50 Pozmix 2% gel. Plug down 7:20 A.M. 1-12-61. WOC 2 hrs. 2nd stage, cemented with 50 sacks 50-50 Pozmix 6% gel. Plug down on second stage 10:45 A.M. 1-12-61. WOC 24 hrs. Pressure tested casing to 1500# for 30 minutes. Pressure held O. K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Tennessee Gas Transmission Company**

Address **P. O. Box 1714**

Durango, Colorado

By **B. Plumb**

Title **District Production Superintendent**